

# Cleanup Site Details

Cleanup Site ID: 1811

|   |                              |                    |                           |                                |                          |
|---|------------------------------|--------------------|---------------------------|--------------------------------|--------------------------|
| <b>Cleanup Site ID:</b> 1811                      | <b>Facility/Site ID:</b> 680 | <b>UST ID:</b> N/A | <a href="#">Site Page</a> | <a href="#">Site Documents</a> | <a href="#">View Map</a> |
| <b>Cleanup Site Name:</b> Northwest Pipeline Mead |                              |                    |                           |                                | <a href="#">Glossary</a> |
| <b>Alternate Names:</b> NORTHWEST PIPELINE MEAD   |                              |                    |                           |                                |                          |

|                             |                              |                        |                                |                                  |                        |
|-----------------------------|------------------------------|------------------------|--------------------------------|----------------------------------|------------------------|
| <b>LOCATION</b>             |                              |                        |                                |                                  |                        |
| <b>Address:</b> N MARKET ST | <b>City:</b> MEAD            | <b>Zip Code:</b> 99021 | <b>County:</b> Spokane         |                                  |                        |
| <b>Latitude:</b> 47.74045   | <b>Longitude:</b> -117.37383 | <b>WRIA:</b> 55        | <b>Legislative District:</b> 7 | <b>Congressional District:</b> 5 | <b>TRS:</b> 26N 43E 21 |

|                                     |   |   |                      |  |  |
|-------------------------------------|---|---|----------------------|--|--|
| <b>DETAIL</b>                       |   |   |                      |  |  |
| <b>Status:</b> No Further Action    | <b>NFA Received?</b> Yes                            | <b>Is PSI site?</b> No                  |                      |  |  |
| <b>Statute:</b> MTCA                | <b>NFA Date:</b> 4/15/2013                          | <b>Current VCP?</b> No                  | <b>Past VCP?</b> Yes |  |  |
| <b>Site Rank:</b> 3 - Moderate Risk | <b>NFA Reason:</b> Voluntary Cleanup Program Review | <b>Brownfield?</b> No                   |                      |  |  |
| <b>Site Manager:</b> Eastern Region | <b>Responsible Unit:</b> Eastern                    | <b>Active Institutional Control?</b> No |                      |  |  |

| <b>CLEANUP UNITS</b>    |           |                            |           |                |                            |
|-------------------------|-----------|----------------------------|-----------|----------------|----------------------------|
| Cleanup Unit Name       | Unit Type | Unit Status                | Resp Unit | Unit Manager   | Current Process            |
| Northwest Pipeline Mead | Upland    | No Further Action Required | EA        | Eastern Region | Standard Voluntary Cleanup |

| <b>ACTIVE INSTITUTIONAL CONTROLS</b>                                 |                   |                           |      |                  |                  |            |
|--|-------------------|---------------------------|------|------------------|------------------|------------|
| Instrument Type  | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
| There are no current Institutional Controls in effect for this site. |                   |                           |      |                  |                  |            |

| <b>AFFECTED MEDIA &amp; CONTAMINANTS</b>   |      |             |               |          |     |         |
|--|------|-------------|---------------|----------|-----|---------|
| <b>MEDIA</b>   |      |             |               |          |     |         |
| Contaminant  | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Metals Priority Pollutants   | RB   |             |               |          |     |         |
| <b>Key:</b><br>B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above<br>S - Suspected                      R - Remediated    RB - Remediated-Below |      |             |               |          |     |         |

| <b>SITE ACTIVITIES</b>                                 |           |            |                          |
|--|-----------|------------|--------------------------|
| Activity   | Status    | Start Date | End Date/Completion Date |
| Initial Investigation / Federal Preliminary Assessment | Completed |            | 5/17/1991                |
| Early Notice Letter(s)                                 | Completed |            | 6/24/1991                |
| Site Hazard Assessment/Federal Site Inspection         | Completed | 2/21/1995  | 6/29/1995                |
| Hazardous Sites Listing/NPL                            | Completed |            | 8/22/1995                |
| VCP Receipt of Plan or Report                          | Completed |            | 12/13/2012               |
| VCP Opinion on Site Cleanup                            | Completed | 12/13/2012 | 2/25/2013                |
| Site Status Changed to NFA                             | Completed |            | 4/15/2013                |
| Remove site from Hazardous Sites List                  | Completed |            | 4/17/2013                |