Cleanup Site Details

Cleanup Site ID: 1856

Cleanup Site ID: 1856 **Facility/Site ID:** 570 **UST ID:** N/A Site Page Site Documents View Map

Cleanup Site Name: Washtucna Grange Supply Glossary

Alternate Names: Original Benge Property, WASHTUCNA GRANGE SUPPLY

LOCATION

Address: WASHTUCNA BENGE RALSTON BENGE RD **City:** BENGE **Zip Code:** 99105 **County:** Adams

Latitude: 46.90834 **Longitude:** -118.10283 **WRIA:** 34 **Legislative District:** 9 **Congressional District:** 4 **TRS:** 16N 37E 1

DETAIL

Status: Awaiting Cleanup **NFA Received?** No **Is PSI site?** No

Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No

Site Rank: 3 - Moderate Risk **NFA Reason:** N/A **Brownfield?** No

Site Manager: Eastern Region **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
WASHTUCNA GRANGE SUPPLY	Upland	Awaiting Cleanup	EA	Eastern Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Petroleum Products-Unspecified	C	S	S		S	

Key:
B - Below Cleanup Level
S - Suspected
C - Confirmed Above Cleanup Level
R - Remediated
RA - Remediated-Above
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/1/1994
Initial Investigation / Federal Preliminary Assessment	Completed		10/17/1994
Early Notice Letter(s)	Completed		10/17/1994
Site Hazard Assessment/Federal Site Inspection	Completed	8/27/2003	2/3/2004
Hazardous Sites Listing/NPL	Completed		2/3/2004