DEPARTMENT OF ECOLOGY State of Washington				Cleanup Site Details						Cleanup Site ID: 187			
Cleanup Site ID: 187 Facility/Site ID:			353930	2	UST ID: N/A	\		Site Page	<u>Site</u>	Documents	<u>View Map</u>		
Cleanup Site Name: Auburn									<u>Glossary</u>				
Alternate Names: Auburn Auto Wrecking, BATES AUTO WRECKING													
LOCATION													
Address: 512 A ST SE	City: AUBURN Zip Code: 98002						02	County: Kir	g				
Latitude: 47.30278 Longi	WRIA: 10 Legislative District: 30 Congressional						onal Dist	rict: 8 Ti	RS : 21N 5E 18				
DETAIL													
Status: Cleanup Started		NFA	Receiv	ved?	No			Is P	SI site?	No			
Statute: MTCA NFA			Date: N/A			Current VCP? No				P? No P	ast VCP? Yes		
Site Rank: N/A NFA Rea			Reaso	on: N/A Brownf					wnfield?	No			
Site Manager: Northwest Region Resp				e Unit:	Northwest	Active Institutional Control? No							
CLEANUP UNITS													
Cleanup Unit Name Unit Type			Unit S	Status	Resp Unit	Uni	Unit Manager		Current Process				
Auburn Auto Wrecking Upland			Cleanup Started			NW	North	Northwest Region		Independ	ndependent Action		
ACTIVE INSTITUTIONAL CONTROLS													
Instrument Type Restriction Rest				s/Requir	ements		Date Record Num		•	Recording County	Tax Parcel		
There are no current Institutional Controls in effect for this site.													
AFFECTED MEDIA & CONTAMINANTS													
								MEDIA			ediment Air Bedrock		
Contaminant Metals Priority Pollutants				Soi C	I Ground	water	Surface Water		Sediment		Bedrock		
Petroleum Products-Unspecified				c									
Key:	<u>u</u>			0									
Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below													
SITE ACTIVITIES													
Activity							Status		Start Liato		End Date/ ompletion Date		
Site Discovery/Release Report Received							Completed			7/1/2005			
Cleanup Action Plan							Completed		7/1/200	10/1/2005 10/1/20			
VCP Opinion on Cleanup Action							Canceled 7/		7/1/200	05	1/1/1900		