

# Cleanup Site Details

**Cleanup Site ID: 1875**

**Cleanup Site ID:** 1875      **Facility/Site ID:** 2270      **UST ID:** N/A      [Site Page](#)    [Site Documents](#)    [View Map](#)  
**Cleanup Site Name:** Slag Disposal Beckwith Property      [Glossary](#)  
**Alternate Names:** SLAG DISPOSAL BECKWITH PROPERTY, Valley View Apartments

**LOCATION**

**Address:** S 218TH ST & 90TH AVE S      **City:** KENT      **Zip Code:** 98031      **County:** King  
**Latitude:** 47.40615    **Longitude:** -122.21949    **WRIA:** 9      **Legislative District:** 33      **Congressional District:** 9      **TRS:** 22N 5E 7

**DETAIL**

**Status:** No Further Action      **NFA Received?** Yes      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** 12/31/2014      **Current VCP?** No    **Past VCP?** No  
**Site Rank:** 3 - Moderate Risk      **NFA Reason:** Ecology Supervised/Conducted Cleanup      **Brownfield?** No  
**Site Manager:** South, David      **Responsible Unit:** Northwest      **Active Institutional Control?** No

**CLEANUP UNITS**

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
SLAG DISPOSAL BECKWITH PROPERTY	Upland	No Further Action Required	NW	South, David	Ecology-supervised or conducted

**ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

**AFFECTED MEDIA & CONTAMINANTS**

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Corrosive Wastes	RB	RB				
Metals - Other	B					
Metals Priority Pollutants	B					

**Key:**  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected                      R - Remediated                                      RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		2/7/1990
Early Notice Letter(s)	Completed		7/19/1990
Site Hazard Assessment/Federal Site Inspection	Completed	10/1/1990	1/22/1991
Hazardous Sites Listing/NPL	Completed		2/1/1991
Remedial Investigation and/or Feasibility Study	Completed	7/1/1991	12/1/1992
Order/Decree/Amendment	Completed	9/29/1992	2/3/2016
Cleanup Action Plan	Completed	1/1/1993	7/5/1994

# Cleanup Site Details

Cleanup Site ID: 1875

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Cleanup - Construction	Completed	6/1/1996	10/30/1996
O & M	Completed	11/1/1996	12/31/2007
O & M	Completed	8/16/2012	12/31/2014
Remove site from Hazardous Sites List	Completed		8/27/2012
Site Status Changed to NFA	Completed		12/31/2014