

Cleanup Site Details

Cleanup Site ID: 1910

Cleanup Site ID: 1910 Facility/Site ID: 575 UST ID: 8104 Site Page Site Documents View Map

Cleanup Site Name: Pasco Landfill NPL Site

Alternate Names: Pasco Landfill NPL Site, PASCO SANITARY LANDFILL, Resource Recover

LOCATION

Address: KAHLOTUS RD & HWY 12 City: PASCO Zip Code: 99301 County: Franklin

Latitude: 46.25200 Longitude: -119.05400 WRIA: 36 Legislative District: 9 Congressional District: 4 TRS: 9N 30E 22

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: Federal - CERCLA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 0 - NPL Site (Fed HRS Score) NFA Reason: N/A Brownfield? No

Site Manager: Schmidt, Jeremy Responsible Unit: Eastern Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
PASCO SANITARY LANDFILL	Upland	Cleanup Started	EA	Schmidt, Jeremy	Federal-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Other Upland Instrument	Groundwater	Restrict All Ground Water Extraction/Well Installation	5/7/2001		Franklin	multiple
Environmental Covenant	Groundwater, Soil	Prohibit Soil Disturbance, Restrict Land Use, Restrict All Ground Water Extraction/Well Installation	6/13/2019	N/A	Franklin	113580082

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the **Environmental Covenants Registry List**.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Base/Neutral/Acid Organics		С						
Conventional Contaminants, Inorganic	С	S						
Conventional Contaminants, Organic	С	S						
Dioxins/Furans	С							
Halogenated Organics	С	С						
Halogenated Solvents		С						
Metals - Other		С						
Metals Priority Pollutants	С	С						
Non-Halogenated Solvents		С						
Other Non-Halogenated Organics		С						
Other Reactive Wastes	С							
Pesticides-Unspecified	С	S						
Phenolic Compounds	С	С						

Toxics Cleanup Program Report Generated: 6/30/2024 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 1910

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Polychlorinated biPhenyls (PCB)	С	С				
Polycyclic Aromatic Hydrocarbons		С				

Key: B - Below Cleanup Level S - Suspected

C - Confirmed Above Cleanup Level R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date	
Initial Investigation / Federal Preliminary Assessment	Completed		8/8/1984	
Hazardous Sites Listing/NPL	Completed		9/10/1990	
Remedial Investigation and/or Feasibility Study	Completed	8/5/1992	10/1/1999	
Interim Action	Completed	12/13/1996	7/8/1997	
Interim Action	In Process	11/1/1999		
Monitoring	In Process	11/1/1999		
Interim Action - O & M/Monitoring	In Process	11/1/1999		
Interim Action - Construction	Completed	2/1/2002	7/31/2002	
Order/Decree/Amendment	In Process	12/20/2011		
Order/Decree/Amendment	Completed	3/28/2014	4/24/2017	
Cleanup Action Plan	Completed	5/1/2019	10/3/2019	
Order/Decree/Amendment	In Process	8/26/2019		
Cleanup Action - Engineering Design	Completed	11/8/2019	1/15/2021	