

Cleanup Site Details

Cleanup Site ID: 1910

Cleanup Site ID: 1910 Facility/Site ID: 575 UST ID: 8104 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Pasco Landfill NPL Site [Glossary](#)

Alternate Names: Pasco Landfill NPL Site, PASCO SANITARY LANDFILL, Resource Recover

LOCATION

Address: KAHLOTUS RD & HWY 12 City: PASCO Zip Code: 99301 County: Franklin
Latitude: 46.25200 Longitude: -119.05400 WRIA: 36 Legislative District: 9 Congressional District: 4 TRS: 9N 30E 22

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: Federal - CERCLA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Schmidt, Jeremy Responsible Unit: Eastern Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
PASCO SANITARY LANDFILL	Upland	Cleanup Started	EA	Schmidt, Jeremy	Federal-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Other Upland Instrument	Groundwater	Restrict All Ground Water Extraction/Well Installation	5/7/2001		Franklin	multiple
Environmental Covenant	Groundwater, Soil	Prohibit Soil Disturbance, Restrict Land Use, Restrict All Ground Water Extraction/Well Installation	6/13/2019	N/A	Franklin	113580082

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics		C				
Conventional Contaminants, Inorganic	C	S				
Conventional Contaminants, Organic	C	S				
Dioxins/Furans	C					
Halogenated Organics	C	C				
Halogenated Solvents		C				
Metals - Other		C				
Metals Priority Pollutants	C	C				
Non-Halogenated Solvents		C				
Other Non-Halogenated Organics		C				
Other Reactive Wastes	C					
Pesticides-Unspecified	C	S				
Phenolic Compounds	C	C				

Cleanup Site Details

Cleanup Site ID: 1910

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Polychlorinated biPhenyls (PCB)	C	C				
Polycyclic Aromatic Hydrocarbons		C				

Key:

B - Below Cleanup Level

C - Confirmed Above Cleanup Level

RA - Remediated-Above

S - Suspected

R - Remediated

RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		8/8/1984
National Priorities Listing	Completed		9/10/1990
Remedial Investigation and/or Feasibility Study	Completed	8/5/1992	10/1/1999
Interim Action	Completed	12/13/1996	7/8/1997
Interim Action	In Process	11/1/1999	
Monitoring	In Process	11/1/1999	
Interim Action - O & M/Monitoring	In Process	11/1/1999	
Interim Action - Construction	Completed	2/1/2002	7/31/2002
Order/Decree/Amendment	In Process	12/20/2011	
Order/Decree/Amendment	Completed	3/28/2014	4/24/2017
Cleanup Action Plan	Completed	5/1/2019	10/3/2019
Order/Decree/Amendment	In Process	8/26/2019	
Cleanup Action - Engineering Design	Completed	11/8/2019	1/15/2021
SHARP Assessment	Completed		5/9/2024