

Cleanup Site Details

Cleanup Site ID: 1913

Cleanup Site ID: 1913 Facility/Site ID: 607 UST ID: 97561 Site Page Site Documents View Map

Cleanup Site Name: Cenex Harvest States Bulk Plant, Moses Lake

Alternate Names: CENEX BULK PLANT HARVEST STATES MOSES LK, Cenex Harvest States Bulk Plant, Moses Lake, CENEX HARVEST

STATES MOSES LK BULK PLANT, CENEX SERVICE CENTER MOSES LAKE, CENEX SERVICE CENTER UST 97561

LOCATION

Address: 1015 E BROADWAY City: MOSES LAKE Zip Code: 98837 County: Grant

Latitude: 47.13849 Longitude: -119.26393 WRIA: 41 Legislative District: 13 Congressional District: 4 TRS: 19N 28E 14

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 8/6/2014 Current VCP? No Past VCP? Yes

Site Rank: 2 - Moderate-High Risk NFA Reason: Voluntary Cleanup Program Review Brownfield? No

Site Manager: Eastern Region Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
CENEX SERVICE CENTER MOSES LAKE	Upland	No Further Action Required	EA	Eastern Region	Standard Voluntary Cleanup Program	

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	В	В				
Petroleum-Diesel	В	В				
Petroleum-Gasoline	В					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		8/13/1991
Early Notice Letter(s)	Completed		8/28/1991
Site Hazard Assessment/Federal Site Inspection	Completed	8/19/1994	6/29/1995
Hazardous Sites Listing/NPL	Completed		8/22/1995
Non-LUST Ind Report Received	Completed		12/22/2010
VCP Opinion on Site Cleanup	Completed	6/17/2014	8/6/2014
Site Status Changed to NFA	Completed		8/6/2014

Toxics Cleanup Program Report Generated: 5/16/2024 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 1913

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Remove site from Hazardous Sites List	Completed		10/10/2014			