

# Cleanup Site Details

Cleanup Site ID: 1913

Cleanup Site ID: 1913      Facility/Site ID: 607      UST ID: 97561      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Cenex Harvest States Bulk Plant, Moses Lake      [Glossary](#)

**Alternate Names:** CENEX BULK PLANT HARVEST STATES MOSES LK, Cenex Harvest States Bulk Plant, Moses Lake, CENEX HARVEST STATES MOSES LK BULK PLANT, CENEX SERVICE CENTER MOSES LAKE, CENEX SERVICE CENTER UST 97561

## LOCATION

**Address:** 1015 E BROADWAY      **City:** MOSES LAKE      **Zip Code:** 98837      **County:** Grant  
**Latitude:** 47.13849      **Longitude:** -119.26393      **WRIA:** 41      **Legislative District:** 13      **Congressional District:** 4      **TRS:** 19N 28E 14

## DETAIL

**Status:** No Further Action      **NFA Received?** Yes      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** 8/6/2014      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** 2 - Moderate-High Risk      **NFA Reason:** Voluntary Cleanup Program Review      **Brownfield?** No  
**Site Manager:** Eastern Region      **Responsible Unit:** Eastern      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CENEX SERVICE CENTER MOSES LAKE	Upland	No Further Action Required	EA	Eastern Region	Standard Voluntary Cleanup Program

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	B	B				
Petroleum-Diesel	B	B				
Petroleum-Gasoline	B					

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		8/13/1991
Early Notice Letter(s)	Completed		8/28/1991
Site Hazard Assessment/Federal Site Inspection	Completed	8/19/1994	6/29/1995
Hazardous Sites Listing/NPL	Completed		8/22/1995
Non-LUST Ind Report Received	Completed		12/22/2010
VCP Opinion on Site Cleanup	Completed	6/17/2014	8/6/2014
Site Status Changed to NFA	Completed		8/6/2014

# Cleanup Site Details

Cleanup Site ID: 1913

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Remove site from Hazardous Sites List	Completed		10/10/2014