

Cleanup Site Details

Cleanup Site ID: 1921

Cleanup Site ID: 1921 Facility/Site ID: 2329 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: ToxGon Corp Seattle [Glossary](#)

Alternate Names: PENBERTHY ELECTROMELT, REMEDCO, ToxGon Corp Seattle

LOCATION

Address: 631 S 96TH ST City: SEATTLE Zip Code: 98108 County: King
Latitude: 47.51704 Longitude: -122.32602 WRIA: 9 Legislative District: 33 Congressional District: 9 TRS: 23N 4E 5

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA (RCRA Corrective Action) NFA Date: 6/6/2003 Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: Independent Cleanup Reviewed by Ecology Brownfield? No
Site Manager: Yasuda, Dean Responsible Unit: Hazardous Waste Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ToxGon Corp Seattle	Upland	No Further Action Required	HWTR	Yasuda, Dean	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	S	S	S			
Halogenated Organics	S	S	S			
Metals Priority Pollutants	S	S	S			
Non-Halogenated Solvents	S	S	S			
Phenolic Compounds	S	S	S			
Polycyclic Aromatic Hydrocarbons	S	S	S			

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Site Status Changed to NFA	Completed		6/6/2003