

Cleanup Site Details

Cleanup Site ID: 193

Cleanup Site ID: 193 Facility/Site ID: 2922 UST ID: 354 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Harris Avenue Shipyard [Glossary](#)

Alternate Names: Bellingham Port Harris Ave Shipyard, HARRIS AV SHIPYARD, Harris Avenue Shipyard, Maritime Contractors Inc, MCI

LOCATION

Address: 201 Harris Ave City: Bellingham Zip Code: 98225 County: Whatcom
 Latitude: 48.72024 Longitude: -122.51551 WRIA: 1 Legislative District: 40 Congressional District: 2 TRS: 37N 2E 2

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
 Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
 Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No
 Site Manager: Rapp, John Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Harris Avenue Shipyard	Sediment	Cleanup Started	NW	Yang, Grant	Ecology-supervised or conducted
Harris Avenue Shipyard	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic				C		
Base/Neutral/Acid Organics	C					
Metals - Other	C	C	S	C		
Metals Priority Pollutants	C	C	S	C		
Petroleum-Other		C				
Phenolic Compounds			S	C		
Polychlorinated biPhenyls (PCB)	B	B	S	C		
Polycyclic Aromatic Hydrocarbons	C	B	S			

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Site Discovery/Release Report Received	Completed		3/30/1993

Cleanup Site Details

Cleanup Site ID: 193

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		10/26/1993
Early Notice Letter(s)	Completed		4/29/1994
Site Hazard Assessment/Federal Site Inspection	Completed	4/6/1995	6/29/1995
Hazardous Sites Listing/NPL	Completed		8/22/1995
VCP Opinion on Remedial Investigation Work Plan	Canceled	4/21/1998	1/1/1900
Remedial Investigation and/or Feasibility Study	Completed	5/1/2002	10/1/2002
Remedial Investigation and/or Feasibility Study	Completed	8/25/2003	12/30/2008
Site Hazard Assessment/Federal Site Inspection	Completed	12/27/2023	1/4/2024