

Cleanup Site Details

Cleanup Site ID: 1937

Cleanup Site ID: 1937 Facility/Site ID: 93453337 UST ID: 11448 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Robys Services [Glossary](#)

Alternate Names: Robys Servic Station Former, ROBYS SERVICES, ROBYS SERVICES OF BUENA

LOCATION

Address: 800 Buena Rd City: BUENA Zip Code: 98921 County: Yakima

Latitude: 46.42988 Longitude: -120.31450 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS:

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 8/5/2016 **Current VCP?** No **Past VCP?** No
Site Rank: 3 - Moderate Risk **NFA Reason:** Ecology Supervised/Conducted Cleanup **Brownfield?** No
Site Manager: Monahan, Mary **Responsible Unit:** Central **Active Institutional Control?** Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Robys Services	Upland	No Further Action Required	CE	Monahan, Mary	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Prohibit Soil Disturbance	3/1/2016	7901322	Yakima	201121-11019

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Gasoline	RA	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Site Characterization Report	Completed		
Early Notice Letter(s)	Completed		10/27/1997
Site Discovery/Release Report Received	Completed		4/9/2001
LUST - Notification	Completed		4/9/2001
Site Hazard Assessment/Federal Site Inspection	Completed	1/4/2012	6/18/2012
Interim Action - Plan	Completed	1/11/2012	4/16/2012
Hazardous Sites Listing/NPL	Completed		6/18/2012
Interim Action - Construction	Completed	11/1/2012	11/16/2012
Interim Action - Performance Monitoring	Completed	11/16/2012	2/23/2015

Cleanup Site Details

Cleanup Site ID: 1937

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Monitoring	Completed	2/25/2013	11/19/2014
LUST - Report Received	Completed		6/6/2013
LUST - Report Received	Completed		6/20/2014
Early Notice Letter(s)	Completed		8/5/2014
Remove site from Hazardous Sites List	Completed		8/5/2016
Site Status Changed to NFA	Completed		8/5/2016
Periodic Review	Completed	3/9/2021	7/31/2022
Periodic Review	Planned	5/1/2027	7/1/2027