DEPARTMENT OF ECOLOGY State of Washington

Cleanup Site Details

Cleanup Site ID: 1937

Cleanup Site ID: 1937 **Facility/Site ID:** 93453337 **UST ID:** 11448 Site Page | Site Documents | View Map

Cleanup Site Name: Robys Services Glossary

Alternate Names: Robys Servic Station Former, ROBYS SERVICES, ROBYS SERVICES OF BUENA

LOCATION

Address: 800 Buena Rd **City:** BUENA **Zip Code:** 98921 **County:** Yakima

Latitude: 46.42988 **Longitude:** -120.31450 **WRIA:** 37 **Legislative District:** 15 **Congressional District:** 4 **TRS:**

DETAIL

Status:	No Further Action	**NFA Received?**	Yes	**Is PSI site?**	No
Statute:	MTCA	**NFA Date:**	8/5/2016	**Current VCP?**	No **Past VCP?** No
Site Rank:	3 - Moderate Risk	**NFA Reason:**	Ecology Supervised/Conducted Cleanup	**Brownfield?**	No
Site Manager:	Monahan, Mary	**Responsible Unit:**	Central	**Active Institutional Control?**	Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Robys Services	Upland	No Further Action Required	CE	Monahan, Mary	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Prohibit Soil Disturbance	3/1/2016	7901322	Yakima	201121-11019

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the **Environmental Covenants Registry List**.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Petroleum-Gasoline	RA	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Site Characterization Report	Completed		1/1/1900
Early Notice Letter(s)	Completed		10/27/1997
Site Discovery/Release Report Received	Completed		4/9/2001
LUST - Notification	Completed		4/9/2001
Site Hazard Assessment	Completed	1/4/2012	6/18/2012
Interim Action - Plan	Completed	1/11/2012	4/16/2012
Hazardous Sites Listing	Completed		6/18/2012
Interim Action - Construction	Completed	11/1/2012	11/16/2012
Interim Action - Performance Monitoring	Completed	11/16/2012	2/23/2015

Cleanup Site Details

Cleanup Site ID: 1937

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Monitoring	Completed	2/25/2013	11/19/2014
LUST - Report Received	Completed		6/6/2013
LUST - Report Received	Completed		6/20/2014
Early Notice Letter(s)	Completed		8/5/2014
Remove site from Hazardous Sites List	Completed		8/5/2016
Site Status Changed to NFA	Completed		8/5/2016
Periodic Review	Completed	3/9/2021	7/31/2022
Periodic Review	Planned	5/1/2027	7/1/2027