

# Cleanup Site Details

Cleanup Site ID: 1937

Cleanup Site ID: 1937      Facility/Site ID: 93453337      UST ID: 11448      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Robys Services      [Glossary](#)

Alternate Names: Robys Servic Station Former, ROBYS SERVICES, ROBYS SERVICES OF BUENA

## LOCATION

Address: 800 Buena Rd      City: BUENA      Zip Code: 98921      County: Yakima

Latitude: 46.42988      Longitude: -120.31450      WRIA: 37      Legislative District: 15      Congressional District: 4      TRS:

## DETAIL

<b>Status:</b> No Further Action	<b>NFA Received?</b> Yes	<b>Is PSI site?</b> No
<b>Statute:</b> MTCA	<b>NFA Date:</b> 8/5/2016	<b>Current VCP?</b> No <b>Past VCP?</b> No
<b>Site Rank:</b> 3 - Moderate Risk	<b>NFA Reason:</b> Ecology Supervised/Conducted Cleanup	<b>Brownfield?</b> No
<b>Site Manager:</b> Monahan, Mary	<b>Responsible Unit:</b> Central	<b>Active Institutional Control?</b> Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Robys Services	Upland	No Further Action Required	CE	Monahan, Mary	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Prohibit Soil Disturbance	3/1/2016	7901322	Yakima	201121-11019

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Gasoline	RA	RB				

**Key:**  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Site Characterization Report	Completed		1/1/1900
Early Notice Letter(s)	Completed		10/27/1997
Site Discovery/Release Report Received	Completed		4/9/2001
LUST - Notification	Completed		4/9/2001
Site Hazard Assessment	Completed	1/4/2012	6/18/2012
Interim Action - Plan	Completed	1/11/2012	4/16/2012
Hazardous Sites Listing	Completed		6/18/2012
Interim Action - Construction	Completed	11/1/2012	11/16/2012
Interim Action - Performance Monitoring	Completed	11/16/2012	2/23/2015

# Cleanup Site Details

Cleanup Site ID: 1937

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Monitoring	Completed	2/25/2013	11/19/2014
LUST - Report Received	Completed		6/6/2013
LUST - Report Received	Completed		6/20/2014
Early Notice Letter(s)	Completed		8/5/2014
Remove site from Hazardous Sites List	Completed		8/5/2016
Site Status Changed to NFA	Completed		8/5/2016
Periodic Review	Completed	3/9/2021	7/31/2022
Periodic Review	Planned	5/1/2027	7/1/2027