

Cleanup Site Details

Cleanup Site ID: 1937

Cleanup Site ID: 1937 Facility/Site ID: 93453337 UST ID: 11448 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Robys Services

[Glossary](#)

Alternate Names: Robys Servic Station Former, ROBYS SERVICES, ROBYS SERVICES OF BUENA

LOCATION

Address: 800 Buena Rd City: BUENA Zip Code: 98921 County: Yakima

Latitude: 46.42988 Longitude: -120.31450 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS:

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 8/5/2016	Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk	NFA Reason: Ecology Supervised/Conducted Cleanup	Brownfield? No
Site Manager: Monahan, Mary	Responsible Unit: Central	Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Robys Services	Upland	No Further Action Required	CE	Monahan, Mary	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Prohibit Soil Disturbance	3/1/2016	7901322	Yakima	201121-11019

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Gasoline	RA	RB				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Site Characterization Report	Completed		
Early Notice Letter(s)	Completed		10/27/1997
Site Discovery/Release Report Received	Completed		4/9/2001
LUST - Notification	Completed		4/9/2001
Site Hazard Assessment/Federal Site Inspection	Completed	1/4/2012	6/18/2012
Interim Action - Plan	Completed	1/11/2012	4/16/2012
Hazardous Sites Listing/NPL	Completed		6/18/2012
Interim Action - Construction	Completed	11/1/2012	11/16/2012
Interim Action - Performance Monitoring	Completed	11/16/2012	2/23/2015

Cleanup Site Details

Cleanup Site ID: 1937

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Monitoring	Completed	2/25/2013	11/19/2014
LUST - Report Received	Completed		6/6/2013
LUST - Report Received	Completed		6/20/2014
Early Notice Letter(s)	Completed		8/5/2014
Remove site from Hazardous Sites List	Completed		8/5/2016
Site Status Changed to NFA	Completed		8/5/2016
Periodic Review	Completed	3/9/2021	7/31/2022
Periodic Review	Planned	5/1/2027	7/1/2027