

# Cleanup Site Details

**Cleanup Site ID: 1941**

**Cleanup Site ID:** 1941      **Facility/Site ID:** 554      **UST ID:** N/A      [Site Page](#)   [Site Documents](#)   [View Map](#)  
**Cleanup Site Name:** Fifth Wheel Truck Repair      [Glossary](#)  
**Alternate Names:** Fifth Wheel Truck Repair

**LOCATION**

**Address:** 307 E Arlington St      **City:** Yakima      **Zip Code:** 98901      **County:** Yakima  
**Latitude:** 46.58888      **Longitude:** -120.49767      **WRIA:** 37      **Legislative District:** 14      **Congressional District:** 4      **TRS:** 13N 19E 30

**DETAIL**

**Status:** No Further Action      **NFA Received?** Yes      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** 3/11/2024      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** 3 - Moderate Risk      **NFA Reason:** Voluntary Cleanup Program Review      **Brownfield?** No  
**Site Manager:** Parker, Kyle      **Responsible Unit:** Central      **Active Institutional Control?** No

**CLEANUP UNITS**

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Fifth Wheel Truck Repair	Upland	No Further Action Required	CE	Parker, Kyle	Standard Voluntary Cleanup

**ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

**AFFECTED MEDIA & CONTAMINANTS**

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	RB	B				
Benzene	RB	B				
Halogenated Solvents	RB	RB				
Lead	RB	B				
Metals - Other	RB	RB				
Non-Halogenated Solvents	RB	B				
Petroleum-Diesel	RB	B				
Petroleum-Gasoline	RB	B				
Petroleum-Other	RB	B				

**Key:**  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected      R - Remediated      RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/Completion Date
Early Notice Letter(s)	Completed		2/26/1993
Remedial Investigation and/or Feasibility Study	Completed	1/13/1995	1/13/1998

# Cleanup Site Details

Cleanup Site ID: 1941

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Interim Action	Completed	1/13/1995	5/3/2001
Order/Decree/Amendment	Completed	1/13/1995	1/1/1900
Order/Decree/Amendment	Completed	6/16/1995	1/1/1900
Site Hazard Assessment/Federal Site Inspection	Completed	10/15/1996	1/7/1997
Hazardous Sites Listing/NPL	Completed		10/16/1996
Interim Action - Performance Monitoring	Completed	5/3/2001	4/17/2023
VCP Receipt of Plan or Report	Completed		5/11/2020
VCP Opinion on Site Cleanup Plan	Completed	7/20/2020	7/30/2020
VCP Receipt of Plan or Report	Completed		4/19/2023
VCP Opinion on Site Cleanup	Completed	4/19/2023	9/13/2023
Remove site from Hazardous Sites List	Completed		3/11/2024
Site Status Changed to NFA	Completed		3/11/2024