

Cleanup Site Details

Cleanup Site ID: 1949

Cleanup Site ID: 1949 Facility/Site ID: 7096 UST ID: 12133 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: South Wilbur Petroleum Site

[Glossary](#)

Alternate Names: South Wilbur Petroleum Site, WA DOT Wilbur Front St, WA DOT WILBUR MAINTENANCE SHED, WILBUR MAINTENANCE, WILBUR MAINTENANCE SITE

LOCATION

Address: FRONT AVE & KNOX & ANN ST **City:** WILBUR **Zip Code:** 99185 **County:** Lincoln
Latitude: 47.75587 **Longitude:** -118.70334 **WRIA:** 43 **Legislative District:** 13 **Congressional District:** 5 **TRS:** 26N 33E 18

DETAIL

Status: Construction Complete-Performance Monitoring **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Treccani, Sandra **Responsible Unit:** Eastern **Active Institutional Control?** Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
South Wilbur Petroleum Site	Upland	Construction Complete-Performance Monitoring	EA	Treccani, Sandra	Ecology-supervised or conducted
WA DOT - Wilbur Facility	Upland	Construction Complete-Performance Monitoring	EA	Treccani, Sandra	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater	Restrict All Ground Water Extraction/Well Installation	9/13/2005	2005 0437931	Lincoln	

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene		C				
Petroleum Products-Unspecified	C	C				
Petroleum-Other	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		6/6/1991
LUST - Report Received	Completed		11/8/1991
Site Discovery/Release Report Received	Completed		3/7/1995
Initial Investigation / Federal Preliminary Assessment	Completed		4/9/1996
Early Notice Letter(s)	Completed		4/11/1996

Cleanup Site Details

Cleanup Site ID: 1949

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment	Completed	3/10/1999	8/3/1999
Hazardous Sites Listing	Completed		8/17/1999
Order/Decree/Amendment	Completed	3/1/2000	11/1/2004
Remedial Investigation and/or Feasibility Study	Completed	3/20/2000	6/30/2002
Cleanup Action Plan	Completed	7/1/2002	5/1/2003
Order/Decree/Amendment	In Process	8/18/2003	
Cleanup Action - Engineering Design	Completed	3/1/2005	9/30/2005
Cleanup - Construction	Completed	10/1/2005	11/4/2005
Cleanup - Performance Monitoring	Completed	11/5/2005	12/31/2011
O & M	Completed	1/1/2011	12/31/2011
Periodic Review	Completed	2/1/2012	4/1/2012
Cleanup - Performance Monitoring	Completed	1/1/2013	12/31/2013
O & M	Completed	1/1/2013	12/31/2013
Order/Decree/Amendment	In Process	3/4/2013	
Interim Action - Construction	Completed	9/1/2013	10/31/2013
Cleanup - Performance Monitoring	Completed	1/1/2014	12/31/2014
O & M	Completed	1/1/2014	12/31/2014
Cleanup - Performance Monitoring	Completed	1/1/2015	12/31/2016
O & M	Completed	1/1/2016	12/31/2016
Cleanup - Performance Monitoring	Completed	1/1/2017	12/31/2017
O & M	Completed	1/1/2017	12/31/2017
Cleanup - Performance Monitoring	Completed	1/1/2018	12/31/2018
O & M	Completed	1/1/2018	12/31/2018
Periodic Review	Completed	11/1/2018	2/12/2019
Cleanup - Performance Monitoring	Completed	1/1/2019	12/31/2019
O & M	Completed	1/1/2019	12/31/2019
Cleanup - Performance Monitoring	Completed	1/1/2020	12/31/2020
O & M	Completed	1/1/2020	12/31/2020
Cleanup - Performance Monitoring	Completed	1/1/2021	12/31/2021
O & M	Completed	1/1/2021	12/31/2021
Cleanup - Performance Monitoring	Completed	1/1/2023	12/31/2023
Cleanup - Performance Monitoring	Completed	1/1/2024	12/31/2024
O & M	Completed	1/1/2024	12/31/2024
Cleanup - Performance Monitoring	In Process	1/1/2025	
O & M	In Process	1/1/2025	

Cleanup Site Details

Cleanup Site ID: 1949

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Periodic Review	Planned	6/1/2025	1/1/1900