

# Cleanup Site Details

Cleanup Site ID: 1949

**Cleanup Site ID:** 1949      **Facility/Site ID:** 7096      **UST ID:** 12133      [Site Page](#)      [Site Documents](#)      [View Map](#)  
**Cleanup Site Name:** South Wilbur Petroleum Site      [Glossary](#)  
**Alternate Names:** South Wilbur Petroleum Site, WA DOT Wilbur Front ST, WA DOT WILBUR MAINTENANCE SHED, WILBUR MAINTENANCE, WILBUR MAINTENANCE SITE

## LOCATION

**Address:** FRONT AVE & KNOX & ANN ST      **City:** WILBUR      **Zip Code:** 99185      **County:** Lincoln  
**Latitude:** 47.75587      **Longitude:** -118.70334      **WRIA:** 43      **Legislative District:** 13      **Congressional District:** 5      **TRS:** 26N 33E 18

## DETAIL

**Status:** Construction Complete-Performance Monitoring      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** No  
**Site Rank:** 1 - Highest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Treccani, Sandra      **Responsible Unit:** Eastern      **Active Institutional Control?** Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
South Wilbur Petroleum Site	Upland	Construction Complete-Performance Monitoring	EA	Treccani, Sandra	Ecology-supervised or conducted
WA DOT - Wilbur Facility	Upland	Construction Complete-Performance Monitoring	EA	Treccani, Sandra	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater	Restrict All Ground Water Extraction/Well Installation	9/13/2005	2005 0437931	Lincoln	

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene		C				
Petroleum Products-Unspecified	C	C				
Petroleum-Other	C					

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		6/6/1991
LUST - Report Received	Completed		11/8/1991
Site Discovery/Release Report Received	Completed		3/7/1995
Initial Investigation / Federal Preliminary Assessment	Completed		4/9/1996
Early Notice Letter(s)	Completed		4/11/1996

# Cleanup Site Details

Cleanup Site ID: 1949

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Site Hazard Assessment/Federal Site Inspection	Completed	3/10/1999	8/3/1999
Hazardous Sites Listing/NPL	Completed		8/17/1999
Order/Decree/Amendment	Completed	3/1/2000	11/1/2004
Remedial Investigation and/or Feasibility Study	Completed	3/20/2000	6/30/2002
Cleanup Action Plan	Completed	7/1/2002	5/1/2003
Order/Decree/Amendment	In Process	8/18/2003	
Cleanup Action - Engineering Design	Completed	3/1/2005	9/30/2005
Cleanup - Construction	Completed	10/1/2005	11/4/2005
Cleanup - Performance Monitoring	In Process	11/5/2005	
Periodic Review	Completed	2/1/2012	4/1/2012
Order/Decree/Amendment	In Process	3/4/2013	
Periodic Review	Completed	11/1/2018	2/12/2019
Periodic Review	Planned	2/12/2024	