

# Cleanup Site Details

Cleanup Site ID: 1952

Cleanup Site ID: 1952      Facility/Site ID: 11876      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)  
 Cleanup Site Name: Gig Harbor Transmission      [Glossary](#)  
 Alternate Names: GIG HARBOR TRANSMISSION

## LOCATION

Address: 14610 PURDY DR NW      City: GIG HARBOR      Zip Code: 98332      County: Pierce  
 Latitude: 47.39094      Longitude: -122.62652      WRIA: 15      Legislative District: 26      Congressional District: 6      TRS: 22N 1E 13

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? Yes  
 Statute: MTCA      NFA Date: 6/24/2019      Current VCP? No      Past VCP? Yes  
 Site Rank: 3 - Moderate Risk      NFA Reason: Voluntary Cleanup Program Review      Brownfield? No  
 Site Manager: Mullin, Tim      Responsible Unit: Southwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
GIG HARBOR TRANSMISSION	Upland	No Further Action Required	SW	Mullin, Tim	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	RB					
Metals Priority Pollutants	RB	B				
Petroleum Products-Unspecified	RB	B				
Polycyclic Aromatic Hydrocarbons	RB	B				

**Key:**  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		12/9/2009
Early Notice Letter(s)	Completed		12/9/2009
Site Discovery/Release Report Received	Completed		12/9/2009
Site Hazard Assessment/Federal Site Inspection	Completed	10/26/2010	2/9/2011
Hazardous Sites Listing/NPL	Completed		2/9/2011
VCP Receipt of Plan or Report	Completed		5/16/2017
VCP Opinion on Site Cleanup	Completed	5/22/2017	9/27/2017

# Cleanup Site Details

Cleanup Site ID: 1952

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Receipt of Plan or Report	Completed		8/7/2017
VCP Receipt of Plan or Report	Completed		10/25/2017
VCP Opinion on Site Cleanup	Completed	10/25/2017	1/16/2018
VCP Receipt of Plan or Report	Completed		2/27/2018
VCP Receipt of Plan or Report	Completed		10/30/2018
VCP Opinion on Site Cleanup	Completed	1/14/2019	2/25/2019
Petroleum Impacts to Groundwater Model Remedies	Completed		1/17/2019
Remove site from Hazardous Sites List	Completed		6/24/2019
Site Status Changed to NFA	Completed		6/24/2019