

Cleanup Site Details

Cleanup Site ID: 1952

Cleanup Site ID: 1952	Facility/Site ID: 11876	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Gig Harbor Transmission					Glossary
Alternate Names: GIG HARBOR TRANSMISSION					

LOCATION

Address: 14610 PURDY DR NW			City: GIG HARBOR	Zip Code: 98332	County: Pierce
Latitude: 47.39094	Longitude: -122.62652	WRIA: 15	Legislative District: 26	Congressional District: 6	TRS: 22N 1E 13

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? Yes
Statute: MTCA	NFA Date: 6/24/2019	Current VCP? No Past VCP? Yes
Site Rank: 3 - Moderate Risk	NFA Reason: Voluntary Cleanup Program Review	Brownfield? No
Site Manager: Mullin, Tim	Responsible Unit: Southwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
GIG HARBOR TRANSMISSION	Upland	No Further Action Required	SW	Mullin, Tim	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	RB					
Metals Priority Pollutants	RB	B				
Petroleum Products-Unspecified	RB	B				
Polycyclic Aromatic Hydrocarbons	RB	B				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		12/9/2009
Early Notice Letter(s)	Completed		12/9/2009
Site Discovery/Release Report Received	Completed		12/9/2009
Site Hazard Assessment/Federal Site Inspection	Completed	10/26/2010	2/9/2011
Hazardous Sites Listing/NPL	Completed		2/9/2011
VCP Receipt of Plan or Report	Completed		5/16/2017
VCP Opinion on Site Cleanup	Completed	5/22/2017	9/27/2017

Cleanup Site Details

Cleanup Site ID: 1952

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Receipt of Plan or Report	Completed		8/7/2017
VCP Receipt of Plan or Report	Completed		10/25/2017
VCP Opinion on Site Cleanup	Completed	10/25/2017	1/16/2018
VCP Receipt of Plan or Report	Completed		2/27/2018
VCP Receipt of Plan or Report	Completed		10/30/2018
VCP Opinion on Site Cleanup	Completed	1/14/2019	2/25/2019
Petroleum Impacts to Groundwater Model Remedies	Completed		1/17/2019
Remove site from Hazardous Sites List	Completed		6/24/2019
Site Status Changed to NFA	Completed		6/24/2019