

Cleanup Site ID: 1985

## Cleanup Site Details

Facility/Site ID: 579 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 1985

Cleanup Site Name: Pasco Bulk Fuel Terminal Site

Alternate Names: Pasco Bulk Fuel Terminal Site, PORT OF PASCO

LOCATION

Address: AINSWORTH & W 9TH City: PASCO Zip Code: 99301 County: Franklin

Latitude: 46.22351 Longitude: -119.09912 WRIA: 36 Legislative District: 16 Congressional District: 4 TRS: 9N 30E 31

**DETAIL** 

Status: Construction Complete- NFA Received? No Is PSI site? No

Performance Monitoring

Statute: WPCA - Ch. 90.48 RCW NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? Yes

Site Manager: Treccani, Sandra Responsible Unit: Eastern Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Pasco Bulk Fuel Terminal Site	Upland	Construction Complete- Performance Monitoring	EA	Treccani, Sandra	Ecology-supervised or conducted

**ACTIVE INSTITUTIONAL CONTROLS** 

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Arsenic		С					
Base/Neutral/Acid Organics			S				
Halogenated Organics	С	С	S				
Lead		С					
Metals Priority Pollutants	В		S				
Non-Halogenated Solvents	С	С					
Pesticides-Unspecified	В						
Petroleum Products-Unspecified	С	С	С				
Polychlorinated biPhenyls (PCB)	В						
Polycyclic Aromatic Hydrocarbons	В	С	S				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level

S - Suspected R - Remediated RB - Remediated-Below

Toxics Cleanup Program Report Generated: 5/1/2024 Page 1 of 2

RA - Remediated-Above



## Cleanup Site Details

Cleanup	Site	ID:	1985
---------	------	-----	------

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
Site Discovery/Release Report Received	Completed		2/5/1973		
Initial Investigation / Federal Preliminary Assessment	Completed		3/15/1973		
Initial Investigation / Federal Preliminary Assessment	Completed		8/14/1984		
Site Hazard Assessment/Federal Site Inspection	Completed	5/30/1990	8/6/1990		
Hazardous Sites Listing/NPL	Completed		8/31/1990		
Interim Action	Completed	10/15/1992	12/31/1999		
Remedial Investigation and/or Feasibility Study	Completed	10/15/1992	8/31/1997		
Cleanup Action Plan	Completed	11/1/1997	3/31/1999		
Cleanup Action - Engineering Design	Completed	3/31/1999	2/28/2001		
Order/Decree/Amendment	In Process	1/1/2000			
Cleanup - Construction	Completed	5/1/2001	9/1/2006		
Cleanup - Performance Monitoring	In Process	6/1/2002			
Periodic Review	Completed	7/1/2008	1/30/2009		
Periodic Review	Completed	12/1/2017	8/18/2020		
Periodic Review	Planned	8/18/2025			