

Cleanup Site Details

Cleanup Site ID: 2052

Cleanup Site ID: 2052 Facility/Site ID: 2299 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Quadrant Lake Union Center Fremont Ave [Glossary](#)

Alternate Names: QUADRANT LAKE UNION CENTER FREMONT AVE

LOCATION

Address: 3307 FREMONT AVE N City: SEATTLE Zip Code: 98103 County: King
Latitude: 47.64899 Longitude: -122.35004 WRIA: 8 Legislative District: 43 Congressional District: 7 TRS: 25N 4E 18

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 12/29/1998 Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: Site Hazard Assessment Brownfield? No
Site Manager: Cargill, Dan Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
QUADRANT LAKE UNION CENTER FREMONT AVE	Upland	No Further Action Required	NW	Cargill, Dan	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	B	S	S			
Phenolic Compounds	B	S	S			
Polychlorinated biPhenyls (PCB)	B	S	S			

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		10/28/1990
Initial Investigation / Federal Preliminary Assessment	Completed		10/30/1990
Early Notice Letter(s)	Completed		12/7/1990
Site Hazard Assessment/Federal Site Inspection	Completed	2/12/1998	12/29/1998
Site Status Changed to NFA	Completed		12/29/1998