

Cleanup Site Details

Cleanup Site ID: 2088

Cleanup Site ID: 2088 Facility/Site ID: 25378742 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: North Central Petroleum Spill [Glossary](#)

Alternate Names: NORTH CENTRAL PETROLEUM SPILL

LOCATION

Address: SR 17 NEAR MP 123 City: BRIDGEPORT Zip Code: 98813 County: Douglas
Latitude: 47.92465 Longitude: -119.43740 WRIA: 50 Legislative District: 12 Congressional District: 4 TRS: 28N 27E 16

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? Yes Past VCP? Yes
Site Rank: 5 - Lowest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Wise, Tavi Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
North Central Petroleum Spill	Upland	Cleanup Started	CE	Wise, Tavi	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Methyl tertiary-butyl ether		C				
Non-Halogenated Solvents		C				
Petroleum Products-Unspecified					S	
Petroleum-Gasoline	C	C				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Non-LUST Ind Report Received	Completed		4/17/1997
Initial Investigation / Federal Preliminary Assessment	Completed		10/9/1998
Site Discovery/Release Report Received	Completed		11/12/1998
Non-LUST Ind Report Received	Completed		11/12/1998
Early Notice Letter(s)	Completed		12/21/1998
Non-LUST Ind Report Received	Completed		5/27/1999

Cleanup Site Details

Cleanup Site ID: 2088

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		10/22/1999
Non-LUST Ind Report Received	Completed		4/24/2001
Non-LUST Ind Report Received	Completed		10/2/2001
Non-LUST Ind Report Received	Completed		5/10/2002
Non-LUST Ind Report Received	Completed		11/25/2002
Non-LUST Ind Report Received	Completed		11/3/2003
Non-LUST Ind Report Received	Completed		11/15/2004
Site Hazard Assessment/Federal Site Inspection	Completed	3/21/2005	8/9/2006
Non-LUST Ind Report Received	Completed		11/17/2005
Hazardous Sites Listing/NPL	Completed		8/9/2006
Non-LUST Ind Report Received	Completed		10/2/2006
Non-LUST Ind Report Received	Completed		11/5/2007
Non-LUST Ind Report Received	Completed		9/29/2008
Non-LUST Ind Report Received	Completed		10/5/2009
Non-LUST Ind Report Received	Completed		10/14/2010
Non-LUST Ind Report Received	Completed		10/24/2011
Non-LUST Ind Report Received	Completed		10/1/2012
Non-LUST Ind Report Received	Completed		10/18/2013
Non-LUST Ind Report Received	Completed		11/26/2014
Non-LUST Ind Report Received	Completed		10/8/2015
VCP Opinion on Site Cleanup	Completed	10/19/2015	4/11/2018
VCP Status Request	Completed	10/22/2019	12/5/2019
VCP Receipt of Plan or Report	Completed		10/15/2021
VCP Opinion on Remedial Investigation Work Plan	Completed	10/15/2021	5/31/2022
VCP Receipt of Plan or Report	Completed		12/19/2023
VCP Opinion on Remedial Investigation Work Plan	Completed	4/12/2024	10/1/2024