

Cleanup Site Details

Cleanup Site ID: 2096 Facility/Site ID: 2776343 UST ID: 508050 Site Page Site Documents View Map

Cleanup Site Name: Superion Plastics Co Inc

Alternate Names: SUPERION PLASTICS CO INC, Superion Plastics, SUPERLON PLASTICS CO INC

LOCATION

Address: 2116 TAYLOR WAY City: TACOMA Zip Code: 98421 County: Pierce

Latitude: 47.27030 Longitude: -122.38408 WRIA: 10 Legislative District: 27 Congressional District: 9 TRS: 21N 3E 35

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Meng, Sam Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
SUPERLON PLASTICS CO INC	Upland	Cleanup Started	SW	Meng, Sam	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Arsenic	С	С	С				
Base/Neutral/Acid Organics	S	S					
Halogenated Organics		С					
Lead	С	С	С				
Metals - Other	S	S					
Metals Priority Pollutants	S	S	С				
Non-Halogenated Solvents	S	S					
Other Halogenated Organics	С	С					
Other Non-Halogenated Organics	С	С					
Petroleum-Other	С	С					
Phenolic Compounds	S	S					
Polycyclic Aromatic Hydrocarbons	S	S					

Key:

B - Below Cleanup Level S - Suspected C - Confirmed Above Cleanup Level

R - Remediated

RA - Remediated-Above RB - Remediated-Below

Toxics Cleanup Program

Report Generated: 11/8/2025

Page 1 of 2

Cleanup Site ID: 2096



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Order/Decree/Amendment	In Process					
Site Discovery/Release Report Received	Completed		7/28/1990			
Site Discovery/Release Report Received	Completed		2/26/1991			
Initial Investigation / Federal Preliminary Assessment	Completed		7/6/2007			
Early Notice Letter(s)	Completed		7/6/2007			
Site Hazard Assessment	Completed	3/17/2009	1/20/2010			
Interim Action - Plan	Completed	11/10/2009	12/10/2009			
Interim Action - Construction	Completed	12/10/2009	1/26/2012			
Hazardous Sites Listing	Completed		1/20/2010			
Interim Action - Plan	Completed	2/5/2011	5/3/2012			
Remedial Investigation and/or FS Work Plan	Completed	3/1/2011	5/12/2011			
Remedial Investigation and/or FS Work Plan	Completed	7/13/2011	9/19/2011			
Interim Action - Plan	Completed	9/23/2011	9/30/2011			
Interim Action - Construction	Completed	9/23/2011	4/3/2012			
Interim Action - Construction	Completed	9/30/2011	4/5/2012			
Remedial Investigation and/or FS Work Plan	Completed	10/1/2011	12/5/2011			
Interim Action - Plan	Completed	1/1/2012	4/3/2012			
Remedial Investigation and/or FS Work Plan	Completed	1/15/2012	4/5/2012			
Remedial Investigation and/or Feasibility Study	Completed	4/5/2012	10/1/2013			
Remedial Investigation and/or Feasibility Study	Completed	9/1/2014	12/17/2014			
Order/Decree/Amendment	In Process	9/30/2015				
Remedial Investigation and/or Feasibility Study	In Process	3/7/2022				
SHARP Assessment	Completed		7/22/2025			

Cleanup Site ID: 2096