

Cleanup Site Details

Cleanup Site ID: 2096

Cleanup Site ID: 2096 Facility/Site ID: 2776343 UST ID: 508050 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Superlon Plastics Co Inc [Glossary](#)

Alternate Names: SUPERION PLASTICS CO INC, Superlon Plastics, SUPERLON PLASTICS CO INC

LOCATION

Address: 2116 TAYLOR WAY City: TACOMA Zip Code: 98421 County: Pierce
Latitude: 47.27030 Longitude: -122.38408 WRIA: 10 Legislative District: 27 Congressional District: 9 TRS: 21N 3E 35

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Meng, Sam Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
SUPERLON PLASTICS CO INC	Upland	Cleanup Started	SW	Mercuri, Joyce	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C	C			
Base/Neutral/Acid Organics	S	S				
Halogenated Organics		C				
Lead	C	C	C			
Metals - Other	S	S				
Metals Priority Pollutants	S	S	C			
Non-Halogenated Solvents	S	S				
Other Halogenated Organics	C	C				
Other Non-Halogenated Organics	C	C				
Petroleum-Other	C	C				
Phenolic Compounds	S	S				
Polycyclic Aromatic Hydrocarbons	S	S				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 2096

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Site Discovery/Release Report Received	Completed		7/28/1990
Site Discovery/Release Report Received	Completed		2/26/1991
Initial Investigation / Federal Preliminary Assessment	Completed		7/6/2007
Early Notice Letter(s)	Completed		7/6/2007
Site Hazard Assessment/Federal Site Inspection	Completed	3/17/2009	1/20/2010
Interim Action - Plan	Completed	11/10/2009	12/10/2009
Interim Action - Construction	Completed	12/10/2009	1/26/2012
Hazardous Sites Listing/NPL	Completed		1/20/2010
Interim Action - Plan	Completed	2/5/2011	5/3/2012
Remedial Investigation and/or FS Work Plan	Completed	3/1/2011	5/12/2011
Remedial Investigation and/or FS Work Plan	Completed	7/13/2011	9/19/2011
Interim Action - Plan	Completed	9/23/2011	9/30/2011
Interim Action - Construction	Completed	9/23/2011	4/3/2012
Interim Action - Construction	Completed	9/30/2011	4/5/2012
Remedial Investigation and/or FS Work Plan	Completed	10/1/2011	12/5/2011
Interim Action - Plan	Completed	1/1/2012	4/3/2012
Remedial Investigation and/or FS Work Plan	Completed	1/15/2012	4/5/2012
Remedial Investigation and/or Feasibility Study	Completed	4/5/2012	10/1/2013
Remedial Investigation and/or Feasibility Study	Completed	9/1/2014	12/17/2014
Order/Decree/Amendment	In Process	9/30/2015	
Remedial Investigation and/or Feasibility Study	In Process	3/7/2022	