

Cleanup Site Details

Cleanup Site ID: 2116

Cleanup Site ID: 2116 Facility/Site ID: 53482918 UST ID: 5235 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Chevron 97451 [Glossary](#)

Alternate Names: BOB & GARYS CHEVRON, CHEVRON 97451, Chevron USA Inc SS 97451

LOCATION

Address: 2626 BELLEVUE WAY NE City: BELLEVUE Zip Code: 98004 County: King
Latitude: 47.63430 Longitude: -122.20124 WRIA: 8 Legislative District: 48 Congressional District: 9 TRS: 25N 5E 20

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: 4 - Low-Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: PLIA Responsible Unit: Pollution Liability Ins Agcy Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CHEVRON 97451	Upland	Cleanup Started	PLIA	PLIA	PLIA Petroleum Technical

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Methyl tertiary-butyl ether	C	C				
Petroleum Products-Unspecified	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		4/23/1991
LUST - Report Received	Completed		8/21/1991
LUST - Report Received	Completed		10/7/1991
LUST - Report Received	Completed		12/4/1992
LUST - Report Received	Completed		7/19/1993
LUST - Report Received	Completed		1/11/1994
LUST - Report Received	Completed		3/3/1995
LUST - Report Received	Completed		8/9/1995
LUST - Report Received	Completed		4/3/1996

Cleanup Site Details

Cleanup Site ID: 2116

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		8/5/1996
LUST - Report Received	Completed		6/14/2000
LUST - Report Received	Completed		11/2/2000
LUST - Report Received	Completed		2/15/2001
LUST - Report Received	Completed		5/7/2001
LUST - Report Received	Completed		2/4/2002
LUST - Report Received	Completed		2/24/2003
LUST - Report Received	Completed		2/6/2004
LUST - Report Received	Completed		1/7/2005
LUST - Report Received	Completed		2/2/2005
LUST - Report Received	Completed		1/30/2006
LUST - Report Received	Completed		1/11/2007
LUST - Report Received	Completed		7/5/2007
LUST - Report Received	Completed		11/15/2007
LUST - Report Received	Completed		11/21/2007
LUST - Report Received	Completed		3/7/2008
LUST - Report Received	Completed		5/21/2008
LUST - Report Received	Completed		12/8/2008
LUST - Report Received	Completed		12/8/2008
LUST - Report Received	Completed		2/5/2009
LUST - Report Received	Completed		7/16/2009
LUST - Report Received	Completed		8/3/2009
LUST - Report Received	Completed		11/20/2009
VCP Opinion on Site Cleanup	Completed	8/19/2010	11/2/2010
LUST - Report Received	Completed		7/25/2011
Site Hazard Assessment	Completed	5/8/2017	8/3/2018
LUST - Report Received	Completed		2/28/2018
Hazardous Sites Listing	Completed		8/7/2018
LUST - Report Received	Completed		3/28/2019