

Cleanup Site Details

Cleanup Site ID: 219

Cleanup Site ID: 219 **Facility/Site ID:** 2899 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Whatcom Waterway [Glossary](#)
Alternate Names: GP Bio Treatment Lagoon, WHATCOM WATERWAY

LOCATION

Address: W OF HOLLY ST BRIDGE **City:** BELLINGHAM **Zip Code:** 98225 **County:** Whatcom
Latitude: 48.74955 **Longitude:** -122.48952 **WRIA:** 1 **Legislative District:** 42 **Congressional District:** 2 **TRS:**

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** Yes
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Schwarz, Julia **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Whatcom Waterway	Sediment	Cleanup Started	NW	McInerney, Lucy	Ecology-supervised or conducted
Whatcom Waterway	Upland	Cleanup Started	NW	McInerney, Lucy	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	B	B	B			
Conventional Contaminants, Inorganic	B	B	B		B	
Conventional Contaminants, Organic	B	B	B		B	
Halogenated Organics	B	B	B	B		
Metals Priority Pollutants	B	B	B	C	B	
Other Deleterious Substances				C		
Petroleum Products-Unspecified	B	B	B			
Phenolic Compounds	B	B	B	C		
Polychlorinated biPhenyls (PCB)				B		
Polycyclic Aromatic Hydrocarbons	B		B	B		

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 219

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	5/15/1991	6/30/1991
Hazardous Sites Listing/NPL	Completed		8/30/1991
Early Notice Letter(s)	Completed		3/9/1995
Order/Decree/Amendment	Completed	10/6/1995	1/1/1900
Remedial Investigation and/or FS Work Plan	Completed	6/3/1996	8/30/1996
Remedial Investigation and/or Feasibility Study	Completed	8/30/1996	6/29/2007
Order/Decree/Amendment	Completed	5/14/2000	1/1/1900
Interim Action - Plan	Completed	5/14/2000	7/24/2000
Interim Action - Construction	Completed	11/6/2000	2/21/2001
Order/Decree/Amendment	Completed	8/12/2001	1/1/1900
Order/Decree/Amendment	Completed	3/13/2002	1/1/1900
Cleanup Action Plan	Completed	1/29/2003	9/24/2007
Order/Decree/Amendment	Completed	3/14/2005	1/1/1900
Order/Decree/Amendment	Completed	3/14/2005	1/1/1900
Order/Decree/Amendment	In Process	1/22/2007	
Order/Decree/Amendment	In Process	12/13/2010	
Cleanup Action - Engineering Design	In Process	8/19/2011	
Cleanup - Construction	In Process	7/23/2015	
Order/Decree/Amendment	In Process	9/28/2022	
Site Hazard Assessment/Federal Site Inspection	Completed		5/16/2024