

Cleanup Site Details

Cleanup Site ID: 2194

Cleanup Site ID: 2194 Facility/Site ID: 15428546 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Pend Oreille Mine [Glossary](#)

Alternate Names: COMINCO AMERICAN INC, COMINCO AMERICAN INC METALINE FALLS, PEND OREILLE MINE, Pend Oreille Mine Historic Debris Field, TECK COMINCO

LOCATION

Address: 1382 PEND OREILLE MINES RD **City:** METALINE FALLS **Zip Code:** 99153 **County:** Pend Oreille
Latitude: 48.88179 **Longitude:** -117.36004 **WRIA:** 62 **Legislative District:** 7 **Congressional District:** 5 **TRS:** 39N 43E 15

DETAIL

Status: Cleanup Complete-Active O&M/Monitoring **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** Yes
Site Manager: Beck, Kristin **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Tailings Disposal Facility 2	Upland	Construction Complete-Performance Monitoring	EA	Beck, Kristin	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	C	C	S			

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		7/2/2000
Early Notice Letter(s)	Completed		12/9/2004
Order/Decree/Amendment	In Process	1/1/2005	
Remedial Investigation and/or Feasibility Study	Completed	2/11/2005	1/1/2010
Cleanup Action Plan	Completed	11/1/2010	2/1/2011
Cleanup - Construction	Completed	6/1/2011	10/1/2011
O & M	Completed	1/1/2012	1/1/2013
Cleanup - Performance Monitoring	Completed	5/1/2012	5/1/2015
Monitoring	In Process	5/1/2012	

Cleanup Site Details

Cleanup Site ID: 2194

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
O & M	Completed	1/1/2013	1/1/2014
O & M	Completed	1/1/2014	1/1/2015
O & M	Completed	1/1/2015	1/1/2016
O & M	Completed	1/1/2016	1/1/2017
O & M	Completed	1/1/2017	1/1/2018
O & M	Completed	1/1/2018	1/1/2019
O & M	Completed	1/1/2019	1/1/2020
O & M	Completed	1/1/2020	1/1/2021
O & M	In Process	1/1/2021	
Periodic Review	Completed	6/1/2023	9/18/2023
Periodic Review	Planned	9/18/2028	