

# Cleanup Site Details

Cleanup Site ID: 220

Cleanup Site ID: 220      Facility/Site ID: 2913      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Cornwall Avenue Landfill      [Glossary](#)

Alternate Names: CORNWALL AV LANDFILL, CORNWALL AVENUE LANDFILL, GEORGIA PACIFIC DNR 22002353

## LOCATION

Address: CORNWALL AVE      City: BELLINGHAM      Zip Code: 98225      County: Whatcom  
 Latitude: 48.74083      Longitude: -122.49269      WRIA: 1      Legislative District: 40      Congressional District: 2      TRS: 38N 2E 36

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? Yes  
 Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? Yes  
 Site Rank: 2 - Moderate-High Risk      NFA Reason: N/A      Brownfield? No  
 Site Manager: Schwarz, Julia      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CORNWALL AVENUE LANDFILL	Sediment	Cleanup Started	NW	McInerney, Lucy	Ecology-supervised or conducted
Cornwall Avenue Landfill	Upland	Cleanup Started	NW	Adams, Mark	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene					C	
Conventional Contaminants, Inorganic	S	C	S		C	
Conventional Contaminants, Organic				C		
Halogenated Pesticides					C	
Halogenated Solvents					C	
Metals Priority Pollutants	S	C	S	C		
Non-Halogenated Pesticides					S	
Non-Halogenated Solvents					C	
Other Halogenated Organics					C	
Other Non-Halogenated Organics					C	
Pesticides-Unspecified	S					
Polychlorinated biPhenyls (PCB)	S			C		
Polycyclic Aromatic Hydrocarbons				C		

# Cleanup Site Details

Cleanup Site ID: 220

**Key:**

B - Below Cleanup Level  
S - Suspected

C - Confirmed Above Cleanup Level  
R - Remediated

RA - Remediated-Above  
RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		6/1/1992
Site Hazard Assessment/Federal Site Inspection	Completed	6/1/1992	8/15/1992
Early Notice Letter(s)	Completed		7/16/1992
Hazardous Sites Listing/NPL	Completed		8/30/1992
Early Notice Letter(s)	Completed		1/12/1995
VCP Opinion on Remedial Investigation Work Plan	Completed	4/21/1998	1/1/1900
Remedial Investigation and/or Feasibility Study	Completed	6/1/1998	12/13/2013
VCP Status Request	Completed	11/13/2006	5/24/2007
Order/Decree/Amendment	Completed	1/1/2014	12/13/2013
Cleanup Action Plan	Completed	1/1/2014	10/10/2014
Order/Decree/Amendment	In Process	1/1/2014	
Cleanup Action - Engineering Design	In Process	10/11/2014	
Site Hazard Assessment/Federal Site Inspection	Completed		5/16/2024