

Cleanup Site ID: 220

Cleanup Site Details

Facility/Site ID: 2913 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 220

Cleanup Site Name: Cornwall Avenue Landfill

Alternate Names: CORNWALL AV LANDFILL, CORNWALL AVENUE LANDFILL, GEORGIA PACIFIC DNR 22002353

LOCATION

Address: CORNWALL AVE City: BELLINGHAM Zip Code: 98225 County: Whatcom

Latitude: 48.74083 Longitude: -122.49269 WRIA: 1 Legislative District: 40 Congressional District: 2 TRS: 38N 2E 36

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Lai, Shawntine Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CORNWALL AVENUE LANDFILL	Sediment	Cleanup Started	NW	Lai, Shawntine	Ecology-supervised or conducted
Cornwall Avenue Landfill	Upland	Cleanup Started	NW	Lai, Shawntine	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Benzene					С			
Conventional Contaminants, Inorganic	S	С	S		С			
Conventional Contaminants, Organic				С				
Halogenated Pesticides					С			
Halogenated Solvents					С			
Metals Priority Pollutants	S	С	S	С				
Non-Halogenated Pesticides					S			
Non-Halogenated Solvents					С			
Other Halogenated Organics					С			
Other Non-Halogenated Organics					С			
Pesticides-Unspecified	S							
Polychlorinated biPhenyls (PCB)	S			С				
Polycyclic Aromatic Hydrocarbons				С				

Toxics Cleanup Program Report Generated: 10/28/2025 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 220

Key: B - Below Cleanup Level S - Suspected

C - Confirmed Above Cleanup Level R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date	
Site Discovery/Release Report Received	Completed		6/1/1992	
Site Hazard Assessment	Completed	6/1/1992	8/15/1992	
Early Notice Letter(s)	Completed		7/16/1992	
Hazardous Sites Listing	Completed		8/30/1992	
Early Notice Letter(s)	Completed		1/12/1995	
VCP Opinion on Remedial Investigation Work Plan	Completed	4/21/1998	1/1/1900	
Remedial Investigation and/or Feasibility Study	Completed	6/1/1998	12/13/2013	
VCP Status Request	Completed	11/13/2006	5/24/2007	
Order/Decree/Amendment	Completed	1/1/2014	12/13/2013	
Cleanup Action Plan	Completed	1/1/2014	10/10/2014	
Order/Decree/Amendment	In Process	1/1/2014		
Cleanup Action - Engineering Design	In Process	10/11/2014		
SHARP Assessment	Completed		5/16/2024	