

Cleanup Site Details

Cleanup Site ID: 2226

Cleanup Site ID: 2226	Facility/Site ID: 9384296	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Eastmont Junior High School					Glossary
Alternate Names: Eastmont Junior High School					

LOCATION

Address: 270 9TH ST			City: EAST WENATCHEE	Zip Code: 98802	County: Douglas
Latitude: 47.41688	Longitude: -120.28717	WRIA: 44	Legislative District: 12	Congressional District: 8	TRS: 22N 20E 11

DETAIL

Status: Awaiting Cleanup	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: N/A	Brownfield? No
Site Manager: Central Region	Responsible Unit: Central	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Eastmont Junior High School	Upland	Awaiting Cleanup	CE	Central Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		9/4/2002
Early Notice Letter(s)	Completed		11/13/2003