

Cleanup Site Details

Cleanup Site ID: 2247

Cleanup Site ID: 2247 Facility/Site ID: 3151688 UST ID: 10632 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: BNSF Winlock [Glossary](#)

Alternate Names: BNSF WINLOCK, CUMMINGS OIL CO INC, CUMMINGS OIL CO INC UST 10632, FORMER SHELL OIL BULK PLANT

LOCATION

Address: 908 NW KERRON ST City: WINLOCK Zip Code: 98596 County: Lewis
Latitude: 46.49604 Longitude: -122.93797 WRIA: 26 Legislative District: 20 Congressional District: 3 TRS: 12N 2W 28

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? Yes Past VCP? Yes
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Mullin, Tim Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CUMMINGS OIL CO INC	Upland	Cleanup Started	SW	Mullin, Tim	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		6/12/2006
VCP Opinion on Interim Action	Completed	6/12/2006	7/26/2006
VCP Opinion on Cleanup Action Plan	Completed	12/23/2008	3/18/2009
VCP Opinion on Site Cleanup	Completed	5/15/2013	8/12/2013
VCP Receipt of Plan or Report	Completed		1/10/2014
VCP Receipt of Plan or Report	Completed		6/30/2014
VCP Receipt of Plan or Report	Completed		1/26/2015
VCP Receipt of Plan or Report	Completed		2/16/2017
VCP Receipt of Plan or Report	Completed		8/29/2017
VCP Receipt of Plan or Report	Completed		1/22/2018

Cleanup Site Details

Cleanup Site ID: 2247

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Technical Assistance	Completed		3/13/2018
VCP Technical Assistance	Completed		3/13/2018
VCP Receipt of Plan or Report	Completed		10/4/2018
VCP Receipt of Plan or Report	Completed		5/2/2019
VCP Receipt of Plan or Report	Completed		9/3/2019
VCP Technical Assistance	Completed		9/25/2019
VCP Opinion on Site Cleanup	Completed	7/13/2020	3/18/2021
VCP Technical Assistance	Completed		7/20/2022
VCP Status Request	Completed	11/16/2023	12/7/2023
VCP Opinion on Site Cleanup	Canceled	12/7/2023	1/1/1900
VCP Status Request	Completed	1/16/2025	2/13/2025
VCP Receipt of Plan or Report	Completed		2/13/2025
VCP Technical Assistance	Completed		2/13/2025
SHARP Assessment	Completed		2/22/2025