

Cleanup Site Details

Cleanup Site ID: 230

Cleanup Site ID: 230 Facility/Site ID: 1625461 UST ID: 9384 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: BNSF Track Switching Facility [Glossary](#)

Alternate Names: BNSF Track Switching Facility, Wishram Railyard, Wishram WA Line SEG 47 PRINT 402 313

LOCATION

Address: 500 MAIN ST City: WISHRAM Zip Code: 98673 County: Klickitat
Latitude: 45.65655 Longitude: -120.96810 WRIA: 30 Legislative District: 14 Congressional District: 3 TRS: 2N 15E 17

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Mefford, John Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BNSF Track Switching Facility	Upland	Cleanup Started	CE	Mefford, John	Ecology-supervised or conducted
BNSF Tracking Switching Facility	Sediment	Cleanup Started	CE	Mefford, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic		C				
Petroleum-Diesel	C	C				
Petroleum-Other	C	C		C		
Polychlorinated biPhenyls (PCB)	B					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		10/31/2003
Site Discovery/Release Report Received	Completed		11/6/2003
Early Notice Letter(s)	Completed		1/4/2005
Site Hazard Assessment/Federal Site Inspection	Completed	11/8/2006	8/3/2007
Hazardous Sites Listing/NPL	Completed		8/3/2007
Non-LUST Ind Report Received	Completed		10/22/2014

Cleanup Site Details

Cleanup Site ID: 230

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		10/22/2014
Non-LUST Ind Report Received	Completed		10/22/2014
Non-LUST Ind Report Received	Completed		10/22/2014
Non-LUST Ind Report Received	Completed		10/22/2014
Non-LUST Ind Report Received	Completed		10/22/2014
Non-LUST Ind Report Received	Completed		10/22/2014
Non-LUST Ind Report Received	Completed		10/22/2014
Non-LUST Ind Report Received	Completed		10/22/2014
Non-LUST Ind Report Received	Completed		10/27/2014
Order/Decree/Amendment	In Process	1/7/2015	
Remedial Investigation and/or FS Work Plan	Completed	10/7/2015	3/28/2016
Remedial Investigation and/or Feasibility Study	Completed	3/28/2016	3/1/2021
Remedial Investigation and/or FS Work Plan	Completed	9/30/2020	11/19/2021
Remedial Investigation and/or Feasibility Study	Completed	5/5/2021	8/26/2022
Remedial Investigation and/or Feasibility Study	In Process	11/19/2021	
Cleanup Action Plan	In Process	5/26/2022	