

Cleanup Site Details

Cleanup Site ID: 2324

Cleanup Site ID: 2324	Facility/Site ID: 24971643	UST ID: N/A	Site Page	Site Documents	View Map	
Cleanup Site Name: Tacoma Smelter Plume Thurston County					Glossary	
Alternate Names: TACOMA SMELTER PLUME THURSTON CNTY, Tacoma Smelter Plume Thurston County						
LOCATION						
Address: TSP Area Wide Thurston County		City: Area Wide	Zip Code: 98516	County: Thurston		
Latitude: 47.09026	Longitude: -122.74706	WRIA: 13	Legislative District: 22	Congressional District: 10	TRS: 19N 1W 36	
DETAIL						
Status: Cleanup Started	NFA Received? No	Is PSI site? No				
Statute: MTCA	NFA Date: N/A	Current VCP? No	Past VCP? No			
Site Rank: 0 - NPL Site (Fed HRS Score)	NFA Reason: N/A	Brownfield? No				
Site Manager: Abbett, Marian	Responsible Unit: Southwest	Active Institutional Control? No				
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Tacoma Smelter Plume Thurston County	Upland	Cleanup Started	SW	Abbett, Marian	Ecology-supervised or conducted	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C		S			
Metals Priority Pollutants	C		S			
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status		Start Date	End Date/ Completion Date		
Site Hazard Assessment	Completed		6/5/2000	8/31/2009		
National Priorities Listing	Completed			8/20/2009		