

Cleanup Site Details

Cleanup Site ID: 2351

Cleanup Site ID: 2351 Facility/Site ID: 578 UST ID: 9809 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Western Farm Serv Pasco [Glossary](#)

Alternate Names: CROP PRODUCTION SERV INC PASCO, Crop Production Svcs Pasco, PUREGRO COMPANY PASCO, PUREGRO COMPANY UST 11425, PUREGRO COMPANY UST 9809, PUREGRO PASCO, Western Farm Serv Pasco, WESTERN FARM SERVICE INC PASCO, WESTERN FARM SERVICE INC PASCO 2

LOCATION

Address: 3482 N GLADE RD **City:** PASCO **Zip Code:** 99301 **County:** Franklin
Latitude: 46.32195 **Longitude:** -119.12366 **WRIA:** 36 **Legislative District:** 9 **Congressional District:** 4 **TRS:** 10N 29E 25

DETAIL

Status: Construction Complete-Performance Monitoring **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Beck, Kristin **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
PUREGRO COMPANY PASCO	Upland	Construction Complete-Performance Monitoring	EA	Beck, Kristin	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Pesticides-Unspecified	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		5/31/1990
Initial Investigation / Federal Preliminary Assessment	Completed		8/22/1990
Early Notice Letter(s)	Completed		9/13/1990
Site Hazard Assessment	Completed	4/2/1991	5/23/1991
Hazardous Sites Listing	Completed		9/2/1991
Order/Decree/Amendment	Completed	6/1/1997	6/1/2003
Remedial Investigation and/or Feasibility Study	Completed	1/16/1998	7/31/2002
Cleanup Action Plan	Completed	8/1/2002	8/1/2003

Cleanup Site Details

Cleanup Site ID: 2351

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process	4/1/2003	
Cleanup Action - Engineering Design	Completed	8/1/2003	3/31/2004
Cleanup - Construction	Completed	4/1/2004	10/29/2004
Cleanup - Performance Monitoring	In Process	11/1/2004	
Periodic Review	Completed	8/30/2008	8/12/2013
O & M	Completed	1/1/2013	1/1/2014
O & M	Completed	1/1/2014	1/1/2015
O & M	Completed	1/1/2015	1/1/2016
O & M	Completed	1/1/2016	1/1/2017
O & M	Completed	1/1/2017	1/1/2018
O & M	Completed	1/1/2018	1/1/2019
O & M	Completed	1/1/2019	1/1/2020
O & M	Completed	1/1/2020	1/1/2021
O & M	Completed	1/1/2021	1/1/2022
O & M	In Process	1/1/2022	
Periodic Review	Completed	10/1/2023	10/30/2023