

Cleanup Site Details

Cleanup Site ID: 2354

Cleanup Site ID: 2354	Facility/Site ID: 605	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Northwest Pipeline Moses Lake					Glossary
Alternate Names: NORTHWEST PIPELINE MOSES LAKE					

LOCATION

Address: N WHEELER RD	City: MOSES LAKE	Zip Code: 98837	County: Grant
Latitude: 47.13079	Longitude: -119.21501	WRIA: 41	Legislative District: 13
		Congressional District: 4	TRS: 19N 29E 19

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 3/26/2013	Current VCP? No Past VCP? Yes
Site Rank: 3 - Moderate Risk	NFA Reason: Voluntary Cleanup Program Review	Brownfield? No
Site Manager: Eastern Region	Responsible Unit: Eastern	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Northwest Pipeline Moses Lake	Upland	No Further Action Required	EA	Eastern Region	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	RB					
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		5/20/1991
Early Notice Letter(s)	Completed		6/24/1991
Site Hazard Assessment/Federal Site Inspection	Completed	8/19/1994	12/29/1994
Hazardous Sites Listing/NPL	Completed		2/21/1995
VCP Receipt of Plan or Report	Completed		12/13/2012
VCP Opinion on Site Cleanup	Completed	1/13/2013	3/26/2013
Site Status Changed to NFA	Completed		3/26/2013
Remove site from Hazardous Sites List	Completed		4/26/2013