

Cleanup Site Details

Cleanup Site ID: 2368 Facility/Site ID: 76716221 UST ID: 3504 Site Page Site Documents View Map

Cleanup Site ID: 2368

Cleanup Site Name: Barbee Mill Company

Alternate Names: BARBEE MILL, BARBEE MILL CO INC, Barbee Mill Company, BERBEE FOREST PRODUCTS

LOCATION

Address: 4101 LAKE WASHINGTON BLVD N City: RENTON Zip Code: 98065 County: King

Latitude: 47.52879 Longitude: -122.20332 WRIA: 8 Legislative District: 41 Congressional District: 9 TRS: 24N 5E 32

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No

Site Manager: Nale, Cliff Responsible Unit: Northwest Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Barbee Mill Co	Upland	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted
Barbee Mill	Sediment	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted
Barbee Mill Off Property Quendall	Upland	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Ongoing Maintenance of Remedy, Control Stormwater, Maintain/Protect Monitoring System	6/6/2008	2008060600120	King	322405-9034-00
Environmental Covenant	Groundwater, Soil	Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Ongoing Maintenance of Remedy, Maintain/Protect Monitoring System, Control Stormwater	4/21/2023	2023042100021	King	2924059002

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the Environmental Covenants Registry List.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Arsenic	С	С						
Conventional Contaminants, Organic				С				
Lead				С				
Metals - Other				С				
Metals Priority Pollutants	С	С	S					
Other Deleterious Substances				С				
Petroleum Products-Unspecified	С	С	S					
Polycyclic Aromatic Hydrocarbons				С				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

Toxics Cleanup Program Report Generated: 8/23/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Initial Investigation / Federal Preliminary Assessment	Completed		9/30/1998			
Site Discovery/Release Report Received	Completed		9/30/1998			
Early Notice Letter(s)	Completed		12/10/1998			
VCP Opinion on Remedial Investigation Work Plan	Canceled	12/15/1998	1/1/1900			
VCP Opinion on Site Cleanup Plan	Completed	5/15/2006	5/17/2006			
VCP Opinion on Interim Action	Completed	6/21/2006	7/28/2006			
VCP Opinion on Interim Action	Canceled	10/10/2007	1/1/1900			
Site Hazard Assessment	Completed	2/27/2008	7/30/2008			
Order/Decree/Amendment	In Process	5/22/2008				
Hazardous Sites Listing	Completed		7/30/2008			
Order/Decree/Amendment	In Process	6/15/2010				
Order/Decree/Amendment	In Process	4/28/2011				
Remedial Investigation and/or FS Work Plan	Completed	12/7/2020	8/5/2021			
Remedial Investigation and/or Feasibility Study	In Process	8/5/2021				
Cleanup Action Plan	In Process	6/14/2024				

Cleanup Site ID: 2368