

Cleanup Site Details

Cleanup Site ID: 2520

Cleanup Site ID: 2520 **Facility/Site ID:** 1940187 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Crowley Marine Services 8th Ave S [Glossary](#)
Alternate Names: Crowley Marine Services 8th Ave S, CROWLEY MARINE SERVICES INC 8TH AVE S, CROWLEY TERMINAL 8TH AVE S

LOCATION

Address: 7400 8TH AVE S **City:** SEATTLE **Zip Code:** 98108 **County:** King
Latitude: 47.53577 **Longitude:** -122.32156 **WRIA:** 9 **Legislative District:** 11 **Congressional District:** 9 **TRS:** 24N 4E 29

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Sutton, Victoria **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CROWLEY MARINE SERVICES INC 8TH AVE S	Upland	Cleanup Started	NW	Sutton, Victoria	Ecology-supervised or conducted
CROWLEY MARINE SERVICES INC 8TH AVE S	Sediment	Awaiting Cleanup	NW	Sutton, Victoria	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C				
Base/Neutral/Acid Organics	C	C		C		
Metals Priority Pollutants	C	C		C		
Petroleum Products-Unspecified	C	S		S		
Phenolic Compounds	S	S		S		
Polychlorinated biPhenyls (PCB)	C	S		C		
Polycyclic Aromatic Hydrocarbons	C	C		C		

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Site Discovery/Release Report Received	Completed		1/4/1993

Cleanup Site Details

Cleanup Site ID: 2520

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		6/21/2007
Early Notice Letter(s)	Completed		7/31/2007
Site Hazard Assessment/Federal Site Inspection	Completed	9/6/2007	2/5/2008
Hazardous Sites Listing/NPL	Completed		2/5/2008
Remedial Investigation and/or FS Work Plan	Completed	10/12/2009	10/1/2012
Remedial Investigation and/or Feasibility Study	In Process	10/1/2012	
Placement of Lien	Completed	10/9/2015	