

# Cleanup Site Details

Cleanup Site ID: 2539

Cleanup Site ID: 2539      Facility/Site ID: 1202      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: American Plating      [Glossary](#)

Alternate Names: AMERICAN PLATING

## LOCATION

Address: 2110 E D ST      City: TACOMA      Zip Code: 98421      County: Pierce  
Latitude: 47.24325      Longitude: -122.43076      WRIA: 10      Legislative District: 27      Congressional District: 9      TRS: 20N 3E 37

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? Yes  
Statute: MTCA      NFA Date: 6/30/2015      Current VCP? No      Past VCP? No  
Site Rank: 2 - Moderate-High Risk      NFA Reason: Ecology Supervised/Conducted Cleanup      Brownfield? Yes  
Site Manager: Coleman, Marv      Responsible Unit: Southwest      Active Institutional Control? Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
American Plating	Upland	No Further Action Required	SW	Coleman, Marv	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Prohibit Soil Disturbance, Restrict All Ground Water Extraction/Well Installation, Restrict Land Use, Restrict Shellfish and/or Finfish Harvesting, Restrict Sediment Cap Disturbance	11/4/2003	N/A	Pierce	8950001761
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Restrict Domestic Ground Water Extraction/Well Installation, Prohibit Soil Disturbance	10/28/2014	201410280356	Pierce	8950001761

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	RB	RB	B		B	
Metals Priority Pollutants	RA	RA	B		B	

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Order/Decree/Amendment	In Process		
Remedial Investigation and/or Feasibility Study	Completed	7/1/1988	7/31/1988
Remedial Investigation and/or Feasibility Study	Completed	7/31/1988	4/25/2003
Site Hazard Assessment/Federal Site Inspection	Completed	3/7/1997	7/10/1997
Hazardous Sites Listing/NPL	Completed		8/19/1997

# Cleanup Site Details

Cleanup Site ID: 2539

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Cleanup Action Plan	Completed	2/15/2003	4/25/2003
Cleanup Action - Engineering Design	Completed	2/15/2003	4/25/2003
Interim Action	Completed	4/25/2003	7/31/2003
Cleanup Action Plan	Completed	7/31/2003	12/1/2009
Cleanup Action Plan	Completed	9/20/2003	11/24/2003
Cleanup Action Plan	Completed	12/30/2003	10/4/2004
O & M	Completed	2/28/2004	9/30/2011
Cleanup Action - Engineering Design	Completed	10/4/2004	12/22/2011
Cleanup - Construction	Completed	4/9/2012	12/3/2012
Site Status Changed to NFA	Completed		6/30/2015
Remove site from Hazardous Sites List	Completed		7/1/2015
Periodic Review	In Process	12/4/2023	