

Cleanup Site Details

Cleanup Site ID: 2569

Cleanup Site ID: 2569
Facility/Site ID: 9
UST ID: 5351
[Site Page](#)
[Site Documents](#)
[View Map](#)
Cleanup Site Name: Kimberly-Clark Worldwide
[Glossary](#)
Alternate Names: KIMBERLY CLARK CORP, KIMBERLY CLARK CORPORATION, KIMBERLY CLARK TISSUE CO EVERETT, Kimberly Clark Worldwide, KIMBERLY CLARK WORLDWIDE INC, Kimberly-Clark Worldwide, SCOTT PAPER CO, SCOTT PAPER CO EVERETT, SCOTT PAPER CO UST 5351

LOCATION

Address: 2600 FEDERAL AVE
City: EVERETT
Zip Code: 98201
County: Snohomish
Latitude: 47.98572
Longitude: -122.21678
WRIA: 7
Legislative District: 38
Congressional District: 2
TRS: 29N 5E 19

DETAIL

Status: Cleanup Started
NFA Received? No
Is PSI site? Yes
Statute: MTCA
NFA Date: N/A
Current VCP? No
Past VCP? No
Site Rank: 4 - Low-Moderate Risk
NFA Reason: N/A
Brownfield? Yes
Site Manager: Cook, Jason
Responsible Unit: Headquarters
Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Scott Paper Co Everett	Upland	No Further Action Required	NW	Northwest Region	Independent Action
Kimberly-Clark Worldwide	Sediment	Awaiting Cleanup	HQ	Adolphson, Pete	Ecology-supervised or conducted
Kimberly-Clark Worldwide	Upland	Cleanup Started	HQ	Cook, Jason	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C		C		
Benzene	S					
Bioassay Failure				C		
Conventional Contaminants, Inorganic				C		
Dioxins/Furans	C			C		
Halogenated Solvents		S				
Lead	C	C				
Mercury		C		C		
Metals - Other	C	C		C		
Other Deleterious Substances				S		
Other Halogenated Organics	S	S		C		
Other Non-Halogenated Organics	S	C		C		

Cleanup Site Details

Cleanup Site ID: 2569

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	C	C		S		
Petroleum-Gasoline	C	C				
Petroleum-Other	C	S		S		
Phenolic Compounds				C		
Polychlorinated biPhenyls (PCB)	C			C		
Polycyclic Aromatic Hydrocarbons	C	C		C		

Key:

B - Below Cleanup Level
S - Suspected

C - Confirmed Above Cleanup Level
R - Remediated

RA - Remediated-Above
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
LUST - Notification	Completed		11/21/1989
LUST - Report Received	Completed		12/27/1999
Order/Decree/Amendment	In Process	3/28/2012	
Early Notice Letter(s)	Completed		4/5/2012
Interim Action - Plan	Completed	7/2/2012	9/24/2012
Remedial Investigation and/or FS Work Plan	Completed	12/20/2012	11/26/2013
Interim Action - Construction	Completed	8/19/2013	5/30/2014
Remedial Investigation and/or Feasibility Study	In Process	10/1/2013	
Site Hazard Assessment/Federal Site Inspection	Completed	10/23/2013	12/24/2013
Hazardous Sites Listing/NPL	Completed		1/16/2014
Interim Action - Performance Monitoring	Completed	5/1/2014	8/20/2016
Order/Decree/Amendment	In Process	11/30/2017	
Interim Action - Plan	Completed	7/3/2018	12/13/2019
Early Notice Letter(s)	Completed		1/22/2020
Early Notice Letter(s)	Completed		1/29/2020
Interim Action - Construction	Completed	2/12/2020	3/3/2021
Non-LUST Ind Report Received	Completed		3/11/2020
Order/Decree/Amendment	In Process	5/29/2020	
Interim Action - Plan	Completed	4/12/2021	8/5/2021
Interim Action - Construction	In Process	9/1/2021	
Non-LUST Ind Report Received	Completed		3/10/2022
Cleanup Action Plan	Planned	6/30/2023	12/28/2023