

Cleanup Site ID: 2581

Cleanup Site Details

Facility/Site ID: 4438651 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 2581

Cleanup Site Name: Bay Wood Products

Glossary

Alternate Names: BAY WOOD PRODUCTS

LOCATION

Address: 200 W MARINE VIEW DR City: EVERETT Zip Code: 98201 County: Snohomish

Latitude: 48.01686 Longitude: -122.20963 WRIA: 7 Legislative District: 38 Congressional District: 2 TRS: 29N 5E 7

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 4 - Low-Moderate Risk NFA Reason: N/A Brownfield? No

Site Manager: Hargrove, Amy Responsible Unit: Headquarters Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BAY WOOD PRODUCTS	Sediment	Cleanup Started	HQ	Morman, Josh	Ecology-supervised or conducted
BAY WOOD PRODUCTS	Upland	Cleanup Started	HQ	Hargrove, Amy	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction	Restrictions/Requirements	Date	Recording	Recording	Tax Parcel
Instrument Type	Media	Restrictions/Requirements	Date	Number	County	I ax Faicei

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Bioassay Benthic Failures				С		
Dioxins/Furans				С		
Metals Priority Pollutants				S		
Non-Halogenated Solvents				S		
Other Deleterious Substances	S	S		С		
Petroleum Products-Unspecified	S	S		S		
Phenolic Compounds				S		
Polychlorinated biPhenyls (PCB)	S	S		S		
Polycyclic Aromatic Hydrocarbons				S		

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Interim Action	Completed	6/1/1986	12/31/1986

Toxics Cleanup Program Report Generated: 3/31/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Site Characterization	Completed	1/1/1989	6/30/1989			
Interim Action	Completed	9/1/1995	10/31/1995			
Order/Decree/Amendment	In Process	1/1/2008				
Site Hazard Assessment/Federal Site Inspection	Completed	9/15/2008	12/29/2008			
Hazardous Sites Listing/NPL	Completed		1/30/2009			
Remedial Investigation and/or Feasibility Study	In Process	6/9/2009				
Order/Decree/Amendment	In Process	1/1/2012				
Interim Action - Plan	Completed	4/18/2014	10/10/2014			
Cleanup Action Plan	In Process	6/30/2015				
Order/Decree/Amendment	In Process	1/1/2020				
Interim Action - Construction	Completed	12/1/2020	4/30/2021			

Cleanup Site ID: 2581