

Cleanup Site Details

Cleanup Site ID: 2581

Cleanup Site ID: 2581
Facility/Site ID: 4438651
UST ID: N/A
[Site Page](#)
[Site Documents](#)
[View Map](#)
Cleanup Site Name: Bay Wood Products
[Glossary](#)
Alternate Names: BAY WOOD PRODUCTS

LOCATION

Address: 200 W MARINE VIEW DR
City: EVERETT
Zip Code: 98201
County: Snohomish
Latitude: 48.01686
Longitude: -122.20963
WRIA: 7
Legislative District: 38
Congressional District: 2
TRS: 29N 5E 7

DETAIL

Status: Cleanup Started
NFA Received? No
Is PSI site? Yes
Statute: MTCA
NFA Date: N/A
Current VCP? No
Past VCP? No
Site Rank: 4 - Low-Moderate Risk
NFA Reason: N/A
Brownfield? No
Site Manager: Hargrove, Amy
Responsible Unit: Headquarters
Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BAY WOOD PRODUCTS	Sediment	Cleanup Started	HQ	Morman, Josh	Ecology-supervised or conducted
BAY WOOD PRODUCTS	Upland	Cleanup Started	HQ	Hargrove, Amy	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Bioassay Benthic Failures				C		
Dioxins/Furans				C		
Metals Priority Pollutants				S		
Non-Halogenated Solvents				S		
Other Deleterious Substances	S	S		C		
Petroleum Products-Unspecified	S	S		S		
Phenolic Compounds				S		
Polychlorinated biPhenyls (PCB)	S	S		S		
Polycyclic Aromatic Hydrocarbons				S		

Key:
B - Below Cleanup Level
C - Confirmed Above Cleanup Level
RA - Remediated-Above
S - Suspected
R - Remediated
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Order/Decree/Amendment	In Process		

Cleanup Site Details

Cleanup Site ID: 2581

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action	Completed	6/1/1986	12/31/1986
Site Characterization	Completed	1/1/1989	6/30/1989
Interim Action	Completed	9/1/1995	10/31/1995
Site Hazard Assessment/Federal Site Inspection	Completed	9/15/2008	12/29/2008
Hazardous Sites Listing/NPL	Completed		1/30/2009
Remedial Investigation and/or Feasibility Study	In Process	6/9/2009	
Interim Action - Plan	Completed	4/18/2014	10/10/2014
Cleanup Action Plan	In Process	6/30/2015	
Interim Action - Construction	Completed	12/1/2020	4/30/2021