

# Cleanup Site Details

Cleanup Site ID: 2771

<b>Cleanup Site ID:</b> 2771	<b>Facility/Site ID:</b> 1092	<b>UST ID:</b> N/A	<a href="#">Site Page</a>	<a href="#">Site Documents</a>	<a href="#">View Map</a>	
<b>Cleanup Site Name:</b> Olympic Pipeline Company LLC <a href="#">Glossary</a>						
<b>Alternate Names:</b> Castle Rock Station, OLYMPIC PIPELINE CO CASTLE ROCK, OLYMPIC PIPELINE COMPANY, Olympic Pipeline Company LLC						
<b>LOCATION</b>						
<b>Address:</b> 185 KALMBACH RD		<b>City:</b> CASTLE ROCK	<b>Zip Code:</b> 98611	<b>County:</b> Cowlitz		
<b>Latitude:</b> 46.26487	<b>Longitude:</b> -122.88290	<b>WRIA:</b> 26	<b>Legislative District:</b> 20	<b>Congressional District:</b> 3	<b>TRS:</b> 9N 2W 13	
<b>DETAIL</b>						
<b>Status:</b> Cleanup Started	<b>NFA Received?</b> No	<b>Is PSI site?</b> No				
<b>Statute:</b> MTCA	<b>NFA Date:</b> N/A	<b>Current VCP?</b> No		<b>Past VCP?</b> No		
<b>Site Rank:</b> 1 - Highest Assessed Risk	<b>NFA Reason:</b> N/A	<b>Brownfield?</b> No				
<b>Site Manager:</b> Southwest Region	<b>Responsible Unit:</b> Southwest	<b>Active Institutional Control?</b>		No		
<b>CLEANUP UNITS</b>						
<b>Cleanup Unit Name</b>	<b>Unit Type</b>	<b>Unit Status</b>	<b>Resp Unit</b>	<b>Unit Manager</b>	<b>Current Process</b>	
OLYMPIC PIPELINE COMPANY	Upland	Awaiting Cleanup	SW	Southwest Region	No Process	
<b>ACTIVE INSTITUTIONAL CONTROLS</b>						
<b>Instrument Type</b>	<b>Restriction Media</b>	<b>Restrictions/Requirements</b>	<b>Date</b>	<b>Recording Number</b>	<b>Recording County</b>	<b>Tax Parcel</b>
There are no current Institutional Controls in effect for this site.						
<b>AFFECTED MEDIA &amp; CONTAMINANTS</b>						
<b>MEDIA</b>						
<b>Contaminant</b>	<b>Soil</b>	<b>Groundwater</b>	<b>Surface Water</b>	<b>Sediment</b>	<b>Air</b>	<b>Bedrock</b>
Petroleum Products-Unspecified	C	C	C		S	
<b>Key:</b> B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above S - Suspected                      R - Remediated                      RB - Remediated-Below						
<b>SITE ACTIVITIES</b>						
<b>Activity</b>	<b>Status</b>		<b>Start Date</b>	<b>End Date/ Completion Date</b>		
Site Hazard Assessment	Completed		9/1/1991	2/1/1992		
Hazardous Sites Listing	Completed			2/25/1992		
Site Discovery/Release Report Received	Completed			1/1/2003		
Non-LUST Ind Report Received	Completed			2/20/2019		
Non-LUST Ind Report Received	Completed			10/25/2019		
Non-LUST Ind Report Received	Completed			2/13/2025		