

# Cleanup Site Details

Cleanup Site ID: 2796

<b>Cleanup Site ID:</b> 2796	<b>Facility/Site ID:</b> 1018	<b>UST ID:</b> N/A	<a href="#">Site Page</a>	<a href="#">Site Documents</a>	<a href="#">View Map</a>	
<b>Cleanup Site Name:</b> Burlington Environmental LLC Washougal						
<b>Alternate Names:</b> BEI, Burlington Environmental Inc, Burlington Environmental LLC Washougal, Burlington Environmental Washougal, Chemical Processors, Chemical Processors, ChemPro Washougal, Clean Earth/Burlington Environmental Washougal, McClary Columbia Corp, Philip Environmental, Philip Environmental MRW Facility, Philip Service Corp, Philip Services Corp Washougal, PSC Environmental Services, Stericycle						
<b>LOCATION</b>						
<b>Address:</b> 625 S 32ND ST		<b>City:</b> WASHOUGAL	<b>Zip Code:</b> 98671	<b>County:</b> Clark		
<b>Latitude:</b> 45.57232	<b>Longitude:</b> -122.33713	<b>WRIA:</b> 28	<b>Legislative District:</b> 18	<b>Congressional District:</b> 3	<b>TRS:</b> 1N 4E 47	
<b>DETAIL</b>						
<b>Status:</b> Cleanup Started	<b>NFA Received?</b> No	<b>Is PSI site?</b> No				
<b>Statute:</b> MTCA (RCRA Corrective Action)	<b>NFA Date:</b> N/A	<b>Current VCP?</b> No		<b>Past VCP?</b> No		
<b>Site Rank:</b> 1 - Highest Assessed Risk	<b>NFA Reason:</b> N/A	<b>Brownfield?</b> No				
<b>Site Manager:</b> Krupp, Stephanie	<b>Responsible Unit:</b> Hazardous Waste	<b>Active Institutional Control?</b>		No		
<b>CLEANUP UNITS</b>						
<b>Cleanup Unit Name</b>	<b>Unit Type</b>	<b>Unit Status</b>	<b>Resp Unit</b>	<b>Unit Manager</b>	<b>Current Process</b>	
Burlington Environmental LLC Washougal	Sediment	Cleanup Started	SW	Krupp, Stephanie	Ecology-supervised or conducted	
Burlington Environmental LLC Washougal	Upland	Cleanup Started	HWTR	Krupp, Stephanie	Ecology-supervised or conducted	
<b>ACTIVE INSTITUTIONAL CONTROLS</b>						
<b>Instrument Type</b>	<b>Restriction Media</b>	<b>Restrictions/Requirements</b>	<b>Date</b>	<b>Recording Number</b>	<b>Recording County</b>	<b>Tax Parcel</b>
There are no current Institutional Controls in effect for this site.						
<b>AFFECTED MEDIA &amp; CONTAMINANTS</b>						
<b>MEDIA</b>						
<b>Contaminant</b>	<b>Soil</b>	<b>Groundwater</b>	<b>Surface Water</b>	<b>Sediment</b>	<b>Air</b>	<b>Bedrock</b>
Halogenated Organics	C	C	C			
Metals - Other	C	C	C	C		
Metals Priority Pollutants	C	C	C	C		
Non-Halogenated Solvents	C	C	C	C		
Petroleum Products-Unspecified		C				
Phenolic Compounds	C	C		C		
Polycyclic Aromatic Hydrocarbons		C				
<b>Key:</b> B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above S - Suspected                      R - Remediated                      RB - Remediated-Below						
<b>SITE ACTIVITIES</b>						
<b>Activity</b>	<b>Status</b>		<b>Start Date</b>	<b>End Date/ Completion Date</b>		
Site Hazard Assessment	Completed		9/14/1995	12/31/1996		
<b>Toxics Cleanup Program</b> <span style="float: right;"><b>Report Generated: 8/20/2025</b></span> <span style="float: right;"><b>Page 1 of 2</b></span>						

# Cleanup Site Details

Cleanup Site ID: 2796

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Hazardous Sites Listing	Completed		2/18/1997
Interim Action	Completed	3/3/1997	10/31/1997
Remedial Investigation and/or Feasibility Study	In Process	3/13/1997	