

Cleanup Site Details

Cleanup Site ID: 2796

Cleanup Site ID: 2796 Facility/Site ID: 1018 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Burlington Environmental LLC Washougal [Glossary](#)

Alternate Names: BEI, Burlington Environmental Inc, Burlington Environmental LLC Washougal, Burlington Environmental Washougal, Chemical Processors, Chemical Processors, ChemPro Washougal, Clean Earth/Burlington Environmental Washougal, McClary Columbia Corp, Philip Environmental, Philip Environmental MRW Facility, Philip Service Corp, Philip Services Corp Washougal, PSC Environmental Services, Stericycle

LOCATION

Address: 625 S 32ND ST **City:** WASHOUGAL **Zip Code:** 98671 **County:** Clark
Latitude: 45.57232 **Longitude:** -122.33713 **WRIA:** 28 **Legislative District:** 18 **Congressional District:** 3 **TRS:** 1N 4E 47

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA (RCRA Corrective Action) **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Krupp, Stephanie **Responsible Unit:** Hazardous Waste **Active Institutional Control?** No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|--|-----------|-----------------|-----------|------------------|---------------------------------|
| Burlington Environmental LLC Washougal | Sediment | Cleanup Started | SW | Krupp, Stephanie | Ecology-supervised or conducted |
| Burlington Environmental LLC Washougal | Upland | Cleanup Started | HWTR | Krupp, Stephanie | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|--|-------------------|---------------------------|------|------------------|------------------|------------|
| There are no current Institutional Controls in effect for this site. | | | | | | |

AFFECTED MEDIA & CONTAMINANTS

| Contaminant | MEDIA | | | | | |
|----------------------------------|-------|-------------|---------------|----------|-----|---------|
| | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Halogenated Organics | C | C | C | | | |
| Metals - Other | C | C | C | C | | |
| Metals Priority Pollutants | C | C | C | C | | |
| Non-Halogenated Solvents | C | C | C | C | | |
| Petroleum Products-Unspecified | | C | | | | |
| Phenolic Compounds | C | C | | C | | |
| Polycyclic Aromatic Hydrocarbons | | C | | | | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|------------------------|-----------|------------|---------------------------|
| Site Hazard Assessment | Completed | 9/14/1995 | 12/31/1996 |

Cleanup Site Details

Cleanup Site ID: 2796

| SITE ACTIVITIES | | | |
|---|---------------|-------------------|--------------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Hazardous Sites Listing | Completed | | 2/18/1997 |
| Interim Action | Completed | 3/3/1997 | 10/31/1997 |
| Remedial Investigation and/or Feasibility Study | In Process | 3/13/1997 | |