ECOLOG State of Washingt	OF Y		Cleanu	p Site [Deta	ails			Cleanu	ıp Sit	e ID: 2876	
Cleanup Site ID: 28	876 Fa	cility/Site ID: 1	39	UST ID: N/A			Site Pag	<u>e Sit</u>	<u>e Documen</u>	<u>ts</u>	<u>View Map</u>	
Cleanup Site Name	: Gas Works Pa	ark									<u>Glossary</u>	
Alternate Names:	Gas Works Park,	, GAS WORKS	PARK WA NAT	URAL GAS, WA	SHING		TURAL GA	AS SEA	TTLE			
LOCATION												
Address: 2000 N N	IORTHLAKE WA	٩Y		City: SEATTL	E	Zip	Code: 981	103	County: ł	King		
Latitude: 47.64693 Longitude: -122.33434			/RIA: 8 Legislative District: 43			43 (Congressional District: 7 TRS:				25N 4E 18	
DETAIL												
Status: Cleanup Started NFA			Received? No				ls P	SI site	? No			
Statute: MTCA NFA			A Date: N/A			Current VCP? No Past VCP? No						
Site Rank: 1 - Highest Assessed Risk NFA			Reason: N/A Brow				wnfield	nfield? No				
Site Manager: Nale, Cliff Responsible Unit: Northwest Active Institutional Control? Yes												
CLEANUP UNITS												
Cleanup U	Cleanup Unit Name Uni		Unit Status		Resp Unit	Unit Manager			Current Process			
Gas Works Park WA	Natural Gas	Sediment	Cleanup Started		NW	-		E	Ecology-supervised		or conducted	
Gas Works Park Upland			Cleanup Started		NW	N Nale, Cliff		Ecology-supervised		rvised	or conducted	
ACTIVE INSTITUTIO	ONAL CONTRO	LS										
Instrument Type	Restriction Media	Rest	rictions/Requir	rements	D	ate	Record Num		Recording County	3	Tax Parcel	
Environmental Covenant	Groundwater, Soil	Installation, Pro	f Remedy, Proh	rbance, Ongoing ibit Removal or	5/5	/2005	20050505 6	500172	King		249700005; 088801930	
Environmental Covenant Groundwater, Restrict All Ground Wal Soil Installation, Prohibit So Maintenance of Remed Alteration of Existing Bu			und Water Extr bhibit Soil Distur f Remedy, Proh	ance, Ongoing		2005050500172 7		King		249700005; 088801930		
Institutional Control of please see the Envir				cuments' link at t	he top o	f the pa	ige. For mo	re deta	ils on Institut	ional C	controls,	
AFFECTED MEDIA	& CONTAMINA	NTS					MEDI	•				
Contaminant			Soi	il Groundy	Nator	Surfac	e Water	A Sedin	nent A	ir	Bedrock	
Halogenated Organics			30	Ground	water	Sunac	e water	C			Deurock	
Metals Priority Pollut						S						
Petroleum Products-Unspecified				С	С		С					
Polycyclic Aromatic Hydrocarbons			С				-					
Key: B - Below Cleanup L S - Suspected	.evel C-C	Confirmed Abov	e Cleanup Leve	el RA - Remo RB - Remo								
Activity						Status			Date	End Date/		
Prepayment Agreement						Completed				Completion Date 3/1/1988		
Remedial Investigation and/or Feasibility Study						Completed		6/1/1988			6/30/1990	
	on and/or I cash	Sincy Olday				Sublet		5,1,1		0/		
Toxics Cleanu	p Program		Repo	ort Generated	: 8/21	/2025			l	Page	1 of 2	



Cleanup Site Details

SITE ACTIVITIES								
Activity	Status	Start Date	End Date/ Completion Date					
Site Hazard Assessment	Completed		6/21/1988					
Site Hazard Assessment	Completed	6/25/1990	8/15/1990					
Hazardous Sites Listing	Completed		8/15/1990					
Cleanup Action Plan	Completed	10/30/1998	6/18/1999					
Cleanup Action - Engineering Design	Completed	11/1/1999	9/22/2000					
Cleanup - Construction	Completed	4/23/2001	8/27/2001					
Periodic Review	Completed	8/27/2001	1/4/2005					
O & M	Completed	8/27/2001	1/1/2003					
O & M	Canceled	1/1/2003	12/31/2012					
Order/Decree/Amendment	Completed	1/1/2005	8/25/2023					
Remedial Investigation and/or Feasibility Study	Completed	3/18/2005	1/20/2023					
O & M	Completed	11/1/2012	4/1/2013					
O & M	In Process	9/1/2014						
Cleanup Action Plan	Completed	2/28/2023	5/23/2023					
Cleanup Action - Engineering Design	In Process	5/24/2023						
Order/Decree/Amendment	In Process	10/1/2023						
SHARP Assessment	Completed		5/9/2024					