

Cleanup Site Details

Cleanup Site ID: 2891

Cleanup Site ID: 2891 Facility/Site ID: 82434686 UST ID: 3646 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Wash Rack [Glossary](#)

Alternate Names: MARTIN OIL, MT VERNON WASH RACK, WASH RACK

LOCATION

Address: 115 W KINCAID City: MOUNT VERNON Zip Code: 98273 County: Skagit
Latitude: 48.41763 Longitude: -122.33570 WRIA: 3 Legislative District: 40 Congressional District: 1 TRS: 34N 4E 19

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
WASH RACK	Upland	Awaiting Cleanup	NW	Northwest Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	S	C				
Petroleum-Other	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		4/21/1989
Site Discovery/Release Report Received	Completed		4/21/1989
LUST - Report Received	Completed		4/3/1990
LUST - Report Received	Completed		5/30/1990
Initial Investigation / Federal Preliminary Assessment	Completed		2/18/2009
Site Hazard Assessment	Completed	1/14/2013	2/28/2013
Hazardous Sites Listing	Completed		8/1/2013