

Cleanup Site Details

Cleanup Site ID: 3033

Cleanup Site ID: 3033 Facility/Site ID: 101 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Silver Mountain Mine

[Glossary](#)

Alternate Names: Silver Mountain Mine

LOCATION

Address: COUNTY RD 4371 City: LOOMIS Zip Code: 98827 County: Okanogan
Latitude: 48.74487 Longitude: -119.55812 WRIA: 49 Legislative District: 7 Congressional District: 4 TRS: 38N 26E 34

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: Federal - CERCLA NFA Date: 12/6/2021 Current VCP? No Past VCP? No
Site Rank: 0 - NPL Site (Fed HRS Score) NFA Reason: Ecology Supervised/Conducted Cleanup Brownfield? No
Site Manager: Central Region Responsible Unit: Central Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Silver Mountain Mine	Upland	No Further Action Required	CE	Central Region	Federal-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict Domestic Ground Water Extraction/Well Installation, Prevent the Reuse or Relocation of Site Soil	12/4/1996	847844	Okanogan	9826340005

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	RA	RA				
Metals Priority Pollutants	RA	RA				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	Completed	10/1/1988	1/19/1990
Cleanup Action Plan	Completed	1/17/1990	3/27/1990
Cleanup Action - Engineering Design	Completed	6/1/1990	9/1/1990
Cleanup - Construction	Completed	9/9/1991	8/31/1993
Hazardous Sites Listing/NPL	Completed		2/22/1995
O & M	In Process	7/10/1997	
Periodic Review	Completed	4/1/2002	9/16/2002

Cleanup Site Details

Cleanup Site ID: 3033

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Periodic Review	Completed	6/1/2007	2/29/2008
Periodic Review	Completed	5/23/2012	9/20/2012
Periodic Review	Completed	4/20/2017	9/1/2017
Remove site from Hazardous Sites List	Completed		12/6/2021
Site Status Changed to NFA	Completed		12/6/2021
Periodic Review	In Process	9/25/2022	