

# Cleanup Site Details

Cleanup Site ID: 3048

Cleanup Site ID: 3048      Facility/Site ID: 1207      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: D St Petroleum      [Glossary](#)

Alternate Names: D ST PETROLEUM

## LOCATION

Address: 3RD-7TH & D ST      City: TACOMA      Zip Code: 98421      County: Pierce  
Latitude: 47.25770      Longitude: -122.43272      WRIA: 10      Legislative District: 27      Congressional District: 9      TRS: 20N 3E 4

## DETAIL

Status: Construction Complete-Performance Monitoring      NFA Received? No      Is PSI site? Yes  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 4 - Low-Moderate Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Gibson, Danielle      Responsible Unit: Southwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
D ST PETROLEUM	Upland	Construction Complete-Performance Monitoring	SW	Gibson, Danielle	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	C	C	R			
Polycyclic Aromatic Hydrocarbons	C	C	R			

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Remedial Investigation and/or Feasibility Study	Completed	10/12/1987	11/1/1990
Site Hazard Assessment/Federal Site Inspection	Completed	5/1/1990	8/1/1990
Hazardous Sites Listing/NPL	Completed		9/10/1990
Cleanup Action Plan	Completed	12/10/1990	7/17/1991
Cleanup Action - Engineering Design	Completed	9/3/1991	3/3/1992
Order/Decree/Amendment	In Process	9/3/1991	
Cleanup - Construction	Completed	5/3/1992	10/1/1992
O & M	Completed	10/1/1992	10/31/2006

# Cleanup Site Details

Cleanup Site ID: 3048

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Periodic Review	Completed	4/10/2007	5/11/2007
Periodic Review	Canceled	5/11/2012	8/11/2012
Periodic Review	Completed	3/1/2014	6/16/2014
Cleanup - Performance Monitoring	In Process	6/12/2014	
Periodic Review	Planned	3/1/2019	6/16/2019
Monitoring	Completed	1/1/2024	12/31/2024