

# Cleanup Site Details

Cleanup Site ID: 3057

Cleanup Site ID: 3057      Facility/Site ID: 1029      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Fort Vancouver Plywood

[Glossary](#)

Alternate Names: Fort Vancouver Plywood, VANCOUVER PLYWOOD, VANCOUVER PORT FVP

## LOCATION

Address: W 8TH ST      City: VANCOUVER      Zip Code: 98660      County: Clark

Latitude: 45.62847      Longitude: -122.68906      WRIA: 28      Legislative District: 49      Congressional District: 3      TRS:

## DETAIL

<b>Status:</b> Construction Complete- Performance Monitoring	<b>NFA Received?</b> No	<b>Is PSI site?</b> No
<b>Statute:</b> MTCA	<b>NFA Date:</b> N/A	<b>Current VCP?</b> No <b>Past VCP?</b> No
<b>Site Rank:</b> N/A	<b>NFA Reason:</b> N/A	<b>Brownfield?</b> No
<b>Site Manager:</b> Praisewater, Thomas	<b>Responsible Unit:</b> Southwest	<b>Active Institutional Control?</b> Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Fort Vancouver Plywood	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	SW	Praisewater, Thomas	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance	6/14/2000	3226928	Clark	502100000, 502090000, 58920000, 502090001, 502080002, 58919000, and 58918000
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation	4/21/2006	4155720	Clark	502100000, 502090000, 58920000, 502090001, 502080002, 58919000, and 58918000

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C					
Halogenated Organics		C				
Lead	C					
Metals - Other		C				
Petroleum-Diesel	C					
Petroleum-Gasoline	C					
Petroleum-Other	C					
Phenolic Compounds	C					

# Cleanup Site Details

Cleanup Site ID: 3057

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Polycyclic Aromatic Hydrocarbons	C					

**Key:**

B - Below Cleanup Level

C - Confirmed Above Cleanup Level

RA - Remediated-Above

S - Suspected

R - Remediated

RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Interim Action	Completed	10/4/1996	12/31/2001
Early Notice Letter(s)	Completed		11/19/1996
Cleanup - Construction	Completed	7/1/2002	12/31/2002
Periodic Review	Completed	1/1/2003	5/1/2008
O & M	In Process	1/1/2003	
Periodic Review	Completed	11/1/2014	3/9/2015
Periodic Review	Completed	6/1/2020	12/7/2020
Periodic Review	Planned	6/1/2025	12/7/2025