

Cleanup Site Details

Cleanup Site ID: 3057

Cleanup Site ID: 3057 Facility/Site ID: 1029 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Fort Vancouver Plywood Glossary

Alternate Names: Fort Vancouver Plywood, VANCOUVER PLYWOOD, VANCOUVER PORT FVP

LOCATION

Address: W 8TH ST City: VANCOUVER Zip Code: 98660 County: Clark

Latitude: 45.62847 Longitude: -122.68906 WRIA: 28 Legislative District: 49 Congressional District: 3 TRS:

DETAIL

Status: Cleanup Complete-Active NFA Received? No Is PSI site? No

O&M/Monitoring

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Praisewater, Thomas Responsible Unit: Southwest Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Fort Vancouver Plywood	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	SW	Praisewater, Thomas	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance	6/14/2000	3226928	Clark	502100000, 502090000, 58920000, 502090001, 502080002, 58919000, and 58918000
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation	4/21/2006	4155720	Clark	502100000, 502090000, 58920000, 502090001, 502080002, 58919000, and 58918000

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the Environmental Covenants Registry List.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Benzene	С							
Halogenated Organics		С						
Lead	С							
Metals - Other		С						
Petroleum-Diesel	С							
Petroleum-Gasoline	С							
Petroleum-Other	С							
Phenolic Compounds	С							

Toxics Cleanup Program Report Generated: 11/6/2025 Page 1 of 2



Polycyclic Aromatic Hydrocarbons

Contaminant

Cleanup Site Details

С

Cleanup Site ID: 3057 Soil Groundwater **Surface Water** Sediment Air Bedrock

Key:B - Below Cleanup Level
S - Suspected RA - Remediated-Above RB - Remediated-Below C - Confirmed Above Cleanup Level R - Remediated

SITE ACTIVITIES

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Order/Decree/Amendment	In Process					
Interim Action	Completed	10/4/1996	12/31/2001			
Early Notice Letter(s)	Completed		11/19/1996			
Cleanup - Construction	Completed	7/1/2002	12/31/2002			
Periodic Review	Completed	1/1/2003	5/1/2008			
O & M	In Process	1/1/2003				
Periodic Review	Completed	11/1/2014	3/9/2015			
Periodic Review	Completed	6/1/2020	12/7/2020			
Periodic Review	Planned	6/1/2025	12/7/2025			
SHARP Assessment	Completed		8/21/2025			